

General Information

Date & Time: 21, Jul, 2026 15:48

Make	Mitsubishi	Model	L300
YOM	2025	Odo Meter Reading	8,571
Registration No.	NKQ2816	Chassis No.	PAEL65NYSSB003921
CC	2.2	Transmission	M/T
Fuel Type	Diesel	Type of Body	FB Body
Colour	White		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	79.9	76	85	79
2	Boot Lid	67.2	73	59	70
3	Roof	63.3	63	61	65/64
4	Left Front Fender	82.7	87	73	89
5	Left Front Door	73.1	77	73	70
6	Center Panel Left	81.6	76	78	91
7	Left Rear Door				
8	Left Back Panel	95.6	92	93	102
9	Right Front Fender	76.6	76	78	76
10	Right Front Door	67.3	71	65	66
11	Center Panel Right	79.1	80	81	76
12	Right Rear Door				
13	Right Back Panel	88.2	85	101	79

Overall Evaluation :

A

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation :	A	Exterior Evaluation :	C
a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain		A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap	
Remarks (R) Front Trim - Grime - Minimal / (R) Front Floor Mat - Grime - Small / (L) Front Floor Mat - Worked - Small / (L) Front Trim - Grime - Minimal / (L) Front Seat - Grime - Minimal / Sunvisor, Sunglass Holder - Grime - Minimal / (R) Front Seat - Grime - Minimal		Remarks (L) Step, In-panel, Side Spoiler - Scratch - Small / (L) Side Gate - Scratch & Dent - Small / Rear Bumper, Lamps, Panels - Rust, Corrosion - Small / Rear Gate - Scratch - Minimal / Cargo Bed Floor - Scratch - Small / (R) Side Gate - Scratch - Small / (L) Front Door, Molding - Scratch - Small / (R) Front Door, Molding - Scratch - Small / (R) Step, In-panel, Side Spoiler - Scratch - Small / (R) Front Fender, Molding - Scratch - Minimal / Front Panel - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch - Small / (L) Front Fender, Molding - Scratch - Minimal / Roof - Scratch - Minimal	
Frame Evaluation :	A	Functional Evaluation :	A
Remarks Defects not found		Remarks Reverse Camera - N/A - Yes	

Inspector Notes

with LTO plate/with warranty booklet/with incomplete tools with jack/with spare tire/with spare key/hairline scratches on the body