

General Information

Date & Time: 22, Jul, 2026 07:40

Make	Mitsubishi	Model	L300
YOM	2026	Odo Meter Reading	8,166
Registration No.	NLA7960	Chassis No.	PAEL65NYTSB010058
CC	2.2	Transmission	M/T
Fuel Type	Diesel	Type of Body	FB Body
Colour	White		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	89.0	91	87	89
2	Boot Lid	105.3	117	91	108
3	Roof	90.7	83	83	115/82
4	Left Front Fender	95.4	87	103	97
5	Left Front Door	83.3	85	81	84
6	Center Panel Left	98.0	103	95	96
7	Left Rear Door				
8	Left Back Panel	169.3	140	242	126
9	Right Front Fender	88.5	84	94	88
10	Right Front Door	86.6	89	85	87
11	Center Panel Right	92.8	97	89	92
12	Right Rear Door				
13	Right Back Panel	104.2	100	100	113

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : D
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (L) Front Floor Mat - Grime - Minimal / (R) Front Floor Mat - Grime - Small / Rear Seat - Grime - Small / (L) Front Seat - Grime - Minimal / (R) Front Seat - Grime - Minimal / Sunvisor, Sunglass Holder - Grime - Medium / (L) Front Trim - Grime - Small / (R) Front Trim - Grime - Minimal	Remarks (L) Rear Corner Panel - Repair Traces - Yes / Front Panel - Scratch - Small / Front Bumper, Grille, Lamps - Scratch & Dent - Small / (L) Front Door, Molding - Scratch - Small / (L) Center Panel - Scratch & Dent - Minimal / (L) Side Gate - Scratch & Dent - Medium / Rear Bumper, Lamps, Panels - Scratch & Dent - Small / Cargo Bed Floor - Scratch - Medium / Rear Gate - Repair mark - Yes / Rear Gate - Scratch & Dent - Small / (R) Side Gate - Scratch & Dent - Small / (R) Center Panel - Scratch - Small / (R) Front Door, Molding - Scratch & Dent - Small / (R) Front Fender, Molding - Scratch - Small / (L) Front Fender, Molding - Scratch - Minimal / Roof - Scratch & Dent - Small
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Reverse Camera - N/A - Yes

Inspector Notes
with LTO plate, with spare tire and key, with jack, with warranty booklet, no tools, no manual booklet, scratches and dent on exterior, scratches on taillight and headlight, unusual light noise in aircon vent.