

General Information

Date & Time: 22, Jul, 2026 07:36

Make	Mitsubishi	Model	L300
YOM	2026	Odo Meter Reading	14,646
Registration No.	NLB7696	Chassis No.	PAEL65NYTSB010421
CC	2.2	Transmission	M/T
Fuel Type	Diesel	Type of Body	FB Body
Colour	White		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	79.7	78	83	78
2	Boot Lid	75.1	85	64	76
3	Roof	87.4	86	101	91/71
4	Left Front Fender	78.5	81	70	85
5	Left Front Door	73.6	78	70	73
6	Center Panel Left	87.3	89	88	85
7	Left Rear Door				
8	Left Back Panel	123.7	85	183	103
9	Right Front Fender	89.3	94	89	85
10	Right Front Door	74.5	78	73	73
11	Center Panel Right	82.8	85	82	83
12	Right Rear Door				
13	Right Back Panel	91.8	87	86	102

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : A	Exterior Evaluation : E
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Ceiling - Crinkle - Small	Remarks (L) Rear Corner Panel - Repair Traces - Yes / (R) Front Fender, Molding - Scratch - Minimal / (R) Front Door, Molding - Scratch - Small / (R) Center Panel - Scratch - Small / (R) Side Gate - Scratch & Dent - Large / Rear Bumper, Lamps, Panels - Rust, Corrosion - Medium / Rear Gate - Scratch - Medium / Cab Back Panel - Scratch & Dent - Large / Cargo Bed Floor - Scratch - Medium / (L) Side Gate - Scratch & Dent - Large / (L) Front Door, Molding - Scratch & Dent - Small / (L) Center Panel - Scratch - Small / (L) Mirror - Scratch - Minimal / (L) Front Fender, Molding - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch & Dent - Medium / Front Panel - Scratch - Minimal / Roof - Scratch - Minimal
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Reverse Camera - N/A - Yes

Inspector Notes

with warranty booklet and jack, no tools, with spare tire, with LTO plate, minor scratches on headlight and tail light