

General Information

Date & Time: 21, Jul, 2026 15:46

Make	Mitsubishi	Model	L300
YOM	2025	Odo Meter Reading	6,485
Registration No.	NKS4652	Chassis No.	PAEL65NYSSB005311
CC	2.2	Transmission	M/T
Fuel Type	Diesel	Type of Body	FB Body
Colour	White		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	77.8	79	79	76
2	Boot Lid	80.5	90	82	70
3	Roof	67.6	71	68	69/63
4	Left Front Fender	82.9	84	78	87
5	Left Front Door	71.6	72	68	75
6	Center Panel Left	83.4	83	83	84
7	Left Rear Door				
8	Left Back Panel	92.8	89	86	104
9	Right Front Fender	86.0	83	87	89
10	Right Front Door	72.9	75	71	73
11	Center Panel Right	81.8	82	81	83
12	Right Rear Door				
13	Right Back Panel	111.0	110	116	107

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : C
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Rear Seat - Cut, Crack - Medium / (L) Front Seat - Worn - Yes / (R) Front Seat - Grime - Minimal / (R) Front Floor Mat - Missing - Yes / (L) Front Floor Mat - Missing - Yes / Carpet - Worn, Scratch, Cut, Crack - Small / (R) Front Trim - Grime - Minimal / (L) Front Trim - Grime - Minimal / Sunvisor, Sunglass Holder - Grime - Medium	Remarks (R) Step, In-panel, Side Spoiler - Scratch - Small / (R) Front Door, Molding - Scratch - Small / (R) Side Gate - Scratch - Small / Rear Bumper, Lamps, Panels - Rust, Corrosion - Small / Cargo Bed Floor - Scratch - Small / Rear Gate - Scratch - Small / (L) Side Gate - Scratch & Dent - Small / (L) Front Door, Molding - Scratch - Small / (L) Step, In-panel, Side Spoiler - Scratch - Small / (L) Front Fender, Molding - Scratch - Minimal / (R) Front Fender, Molding - Scratch - Minimal / Front Panel - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch - Small / Roof - Scratch - Minimal
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Reverse Camera - N/A - Yes / Turn Signal, Hazard Flasher - Issue - Yes / Lamps (Brake, Tail, Fog) - Issue - Yes / Spare Key - Issue - Unexist

Inspector Notes
with LTO plate/no warranty booklet/no tools and jack/with worn spare tire/no spare key/side mirror issue/tailight issue/signal light issue/rear room light issue/signal light and park light cover issue/acid rain on the body/hairline scratches on the body/traces of adhesive on windows/brake light issue/stereo volume switch issue