

General Information

Date & Time: 28, Jul, 2026 15:18

Make	Toyota	Model	Vios
YOM	2022	Odo Meter Reading	55,288
Registration No.	NER5681	Chassis No.	PA1B18F30M4163823
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Green		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	139.6	154	126	139
2	Boot Lid	116.6	111	118	121
3	Roof	88.1	98	83	85/87
4	Left Front Fender	228.0	216	235	233
5	Left Front Door	457.6	787	174	412
6	Center Panel Left				
7	Left Rear Door	329.0	324	269	394
8	Left Back Panel	193.6	204	208	169
9	Right Front Fender	91.3	95	86	93
10	Right Front Door	98.0	93	98	103
11	Center Panel Right				
12	Right Rear Door	96.3	94	92	103
13	Right Back Panel	114.0	102	121	119

Overall Evaluation :

D

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : E
a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (L) Front Floor Mat - Worked - Small / (R) Front Floor Mat - Grime - Minimal / Mat Other - Worked - Small / Dashboard - Worn, Scratch, Cut, Crack - Minimal / (L) Front Seat - Grime - Minimal / (R) Front Seat - Grime - Minimal / Rear Seat - Worn - Yes / Ceiling - Grime - Small	Remarks (R) Front Door - Repair Traces - Yes / (R) Front Fender - Repair Traces - Yes / (L) Front Fender - Repair Traces - Yes / (L) Front Door - Repair Traces - Yes / (L) Rear Door - Repair Traces - Yes / (L) Rear Fender - Repair Traces - Yes / Trunk Hood, Rear Gate - Repair Traces - Yes / (R) Rear Fender - Repair Traces - Yes / (R) Rear Door - Repair Traces - Yes / Roof - Repair Traces - Yes / (L) Front Fender, Molding - Repair mark - Yes / (L) Front Door, Molding - Repair mark - Yes / (L) Rear Door, Molding - Repair mark - Yes / (L) Rear Fender, Molding - Repair mark - Yes / (R) Front Fender, Molding - Scratch - Medium / (R) Step, In-panel, Side Spoiler - Scratch - Small / (R) Front Door, Molding - Scratch & Dent - Small / (R) Rear Door, Molding - Scratch & Dent - Small / (R) Rear Fender, Molding - Scratch & Dent - Small / Rear Bumper, Lamps, Panels - Scratch - Medium / Trunk Hood, Rear Gate - Scratch - Large / (L) Rear Fender, Molding - Scratch - Minimal / (L) Rear Door, Molding - Scratch - Small / (L) Step, In-panel, Side Spoiler - Repair mark - Yes / (L) Front Door, Molding - Scratch - Minimal / (L) Front Fender, Molding - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch - Large / Bonnet, Headlight - Scratch - Minimal / Roof - Scratch - Minimal / (L) Mirror - Crack - Damaged
Frame Evaluation : D	Functional Evaluation : A
Remarks Left Center Pillar - Traces of Bending, or Marks of Panel Repair ? - Yes	Remarks Parking Brake - Function - Weak / Spare Key - Issue - Unexist

Inspector Notes

with Ito plate/with spare tire/without warranty booklet/with dent and scratches on the body/without spare key/without reverse camera/side mirror adjuster issue