

General Information

Date & Time: 24, Jul, 2026 11:18

Make	Toyota	Model	Vios
YOM	2022	Odo Meter Reading	43,980
Registration No.	DAP7286	Chassis No.	PA1B18F30N4169753
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Black		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	113.3	122	107	111
2	Boot Lid	118.6	111	120	125
3	Roof	100.3	106	98	98/100
4	Left Front Fender	148.3	151	160	134
5	Left Front Door	152.6	155	145	158
6	Center Panel Left				
7	Left Rear Door	151.3	153	155	146
8	Left Back Panel	120.6	130	121	111
9	Right Front Fender	104.0	102	107	103
10	Right Front Door	102.6	99	100	109
11	Center Panel Right				
12	Right Rear Door	383.3	897	122	131
13	Right Back Panel	219.6	378	148	133

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : E
a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Ceiling - Grime - Small / Mat Other - Missing - Yes / Rear Seat - Grime - Small / (R) Front Trim - Grime - Minimal / (R) Front Seat - Grime - Minimal / Trunk Room - Worked - Minimal / (L) Front Floor Mat - Worked - Small / Carpet - Worked - Minimal / (L) Front Trim - Grime - Small	Remarks (R) Rear Fender - Repair Traces - Yes / (R) Rear Door - Repair Traces - Yes / Overall Exterior - Worn as per age - Yes / (R) Front Fender, Molding - Scratch - Medium / (R) Mirror - Scratch - Minimal / (R) Front Door, Molding - Scratch - Large / (R) Rear Door, Molding - Repair mark - Yes / (R) Rear Fender, Molding - Repair mark - Yes / (R) Step, In-panel, Side Spoiler - Scratch - Minimal / (R) Rear Fender, Molding - Scratch - Medium / (R) Rear Door, Molding - Scratch & Dent - Large / Rear Bumper, Lamps, Panels - Scratch - Medium / Trunk Hood, Rear Gate - Scratch - Medium / (L) Rear Fender, Molding - Scratch & Dent - Small / (L) Rear Door, Molding - Scratch - Medium / (L) Front Door, Molding - Scratch & Dent - Medium / (L) Step, In-panel, Side Spoiler - Scratch - Minimal / (L) Mirror - Scratch - Minimal / (L) Front Fender, Molding - Scratch - Medium / Front Bumper, Grille, Lamps - Scratch - Large / Bonnet, Headlight - Scratch & Dent - Medium / Roof - Scratch - Small / Roof Spoiler, Molding - Scratch - Medium
Frame Evaluation : A	Functional Evaluation : C
Remarks Defects not found	Remarks Shift Shock - Function - Weak / Battery - Weak - Yes / Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist

Inspector Notes

NO Lto plate, with spare tire and jack, 1key, no warranty booklet and tools, scratches on headlights and taillights, fuel lid issue, battery weak, possible flooding, visible hairlines scratches on vehicle