

General Information

Date & Time: 25, Jul, 2026 15:57

Make	Suzuki	Model	Ertiga
YOM	2018	Odo Meter Reading	82,161
Registration No.	NAA6424	Chassis No.	MHUZE81S4JJ3082
CC	1.4	Transmission	M/T
Fuel Type	Gas	Type of Body	Wagon
Colour	Black		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	87.4	90	82	90
2	Boot Lid	85.3	80	86	90
3	Roof	84.4	83	86	86/82
4	Left Front Fender	94.8	91	96	98
5	Left Front Door	84.8	89	79	87
6	Center Panel Left				
7	Left Rear Door	83.6	86	78	87
8	Left Back Panel	94.4	102	97	85
9	Right Front Fender	90.8	89	94	90
10	Right Front Door	87.5	84	84	95
11	Center Panel Right				
12	Right Rear Door	151.3	143	156	155
13	Right Back Panel	90.8	89	88	95

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation :	B	Exterior Evaluation :	E
The diagram shows the interior of a vehicle from above. Inspection points are labeled as follows: A1: Driver's side front seat area. A3: Center console area. D3: Passenger's side front seat area. Y1: Front door sill areas. Y2: Rear door sill areas. Numbered areas: 1 (Frontal airbag), 2 (Driver's headrest), 3 (Center console), 4 (Passenger's headrest), 5 (Passenger's seat), 6 (Rear passenger area), 7 (Rear bench seat), 8 (Trunk floor), 9 (Driver's seat), 10 (Left side panel).		The diagram shows the exterior of a vehicle from above. Inspection points are labeled as follows: AU1-AU4: Four wheel arch areas. A1: Front hood/bumper area. A2: Side mirror/fender areas. Y: Rear bumper area. Numbered areas: 1 (Front grille), 2 (Front fender), 3 (Front door), 4 (Front door handle), 5 (Rear door), 6 (Rear door handle), 7 (Rear bumper), 8 (Side mirror), 9 (Side door), 10 (Side door handle), 11 (Side door trim), 12 (Side door lower edge), 13 (Front end), 14 (Front wheel), 15 (Front bumper), 16 (Rear wheel), 17 (Rear bumper).	
a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain		A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap	
Remarks Ceiling - Grime - Minimal / (R) Rear Trim - Grime - Small / (R) Front Trim - Grime - Minimal / Dashboard - Worn, Scratch, Cut, Crack - Minimal / Console, Switches, Vents - Worn, Scratch, Cut, Crack - Medium / Rear Seat - Grime - Small / (L) Rear Trim - Grime - Minimal / (L) Front Trim - Grime - Small / Trim Other - Loose, Deformed - Medium		Remarks (R) Rear Door - Repair Traces - Yes / (R) Front Fender, Molding - Scratch & Dent - Small / (R) Mirror - Scratch - Minimal / (R) Front Door, Molding - Scratch & Dent - Small / (R) Step, In-panel, Side Spoiler - Scratch - Minimal / (R) Rear Door, Molding - Scratch & Dent - Large / (R) Rear Fender, Molding - Scratch & Dent - Large / Rear Bumper, Lamps, Panels - Scratch & Dent - Large / Trunk Hood, Rear Gate - Scratch & Dent - Small / (L) Rear Fender, Molding - Scratch - Small / (L) Rear Door, Molding - Repair mark - Yes / (L) Rear Door, Molding - Scratch & Dent - Small / (L) Front Door, Molding - Scratch & Dent - Medium / (L) Mirror - Scratch - Minimal / (L) Front Fender, Molding - Scratch & Dent - Large / Antennae - Damaged - Yes / Roof - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch & Dent - Large / Bonnet, Headlight - Scratch - Small / (L) Step, In-panel, Side Spoiler - Scratch - Small	
Frame Evaluation :	A	Functional Evaluation :	C
Remarks Defects not found		Remarks Air Conditioner - Function - Weak	

Inspector Notes

With Lto plate, with spare tire, 2keys, no warranty booklet and tools and Jack, faded headlights, scratches on taillights, worn right front tire, aircon issue. rear trim other cover missing.trunk door issue