

General Information

Date & Time: 03, Mar, 2025 09:32

Make	Suzuki	Model	Ertiga
YOM	2023	Mileage	16,740
Registration No.	NNV1843	Chassis No.	MHYNC32S4PJ100504
CC	1.5	Transmission	A/T
Fuel Type	Hybrid	Type of Body	Wagon
Colour	Brown		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	94.3	102	81	100
2	Boot Lid	84.6	85	86	83
3	Roof	87.4	83	91	88/88
4	Left Front Fender	76.7	75	78	77
5	Left Front Door	84.6	91	79	83
6	Center Panel Left				
7	Left Rear Door	88.0	86	84	94
8	Left Back Panel	86.5	90	89	80
9	Right Front Fender	76.7	77	74	80
10	Right Front Door	89.1	85	85	98
11	Center Panel Right				
12	Right Rear Door	88.6	93	83	91
13	Right Back Panel	80.8	84	79	80

Overall Evaluation :

A

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : A	Exterior Evaluation : C
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Defects not found	Remarks Trunk Hood, Rear Gate - Scratch & Dent - Small / (R) Rear Fender, Molding - Scratch - Medium / (R) Rear Door, Molding - Scratch - Small / (R) Front Door, Molding - Scratch & Dent - Small / (R) Front Fender, Molding - Scratch - Small / Front Bumper, Grille, Lamps - Dent - Small / (L) Front Fender, Molding - Scratch & Dent - Small / (L) Front Door, Molding - Scratch - Small / (L) Rear Door, Molding - Scratch - Medium / Rear Bumper, Lamps, Panels - Scratch - Large
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist

Inspector Notes
with warranty plate/ with LTO green plate(hybrid) / with spare tire/ no tools and jack