

General Information

Date & Time: 03, Mar, 2025 18:59

Make	Toyota	Model	Vios
YOM	2024	Mileage	10,271
Registration No.	DBN7717	Chassis No.	PA1B18F30P4233308
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Red Mica Metallic		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	99.0	102	92	103
2	Boot Lid	99.3	95	100	103
3	Roof	91.3	95	93	87/91
4	Left Front Fender	84.4	86	83	85
5	Left Front Door	95.1	92	94	100
6	Center Panel Left				
7	Left Rear Door	93.1	96	94	90
8	Left Back Panel	99.0	104	100	93
9	Right Front Fender	92.7	92	93	93
10	Right Front Door	97.8	100	102	92
11	Center Panel Right				
12	Right Rear Door	91.3	87	93	94
13	Right Back Panel	95.3	97	94	95

Overall Evaluation :

C

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : B	Exterior Evaluation : D
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (R) Front Seat - Grime - Medium / (L) Front Seat - Grime - Medium / (L) Front Floor Mat - Grime - Medium	Remarks Member (Bolted) - Dent - Yes / Front Bumper, Grille, Lamps - Scratch & Dent - Large / (R) Front Fender, Molding - Scratch & Dent - Minimal / Rear Bumper, Lamps, Panels - Scratch - Large / (L) Rear Door, Molding - Scratch - Medium / (R) Rear Fender, Molding - Scratch - Minimal / (R) Rear Door, Molding - Scratch - Small / (L) Front Door, Molding - Scratch - Small / (R) Front Door, Molding - Scratch - Medium / Bonnet, Headlight - Scratch & Dent - Large
Frame Evaluation : B	Functional Evaluation : A
Remarks Front Cross Member Support - Traces of Bending, or Marks of Panel Repair ? - Yes	Remarks Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist

Inspector Notes
with warranty booklet, spare tire, jack but incomplete tools. with LTO plate. Gap at front bumper.