

General Information

Date & Time: 30, Jul, 2026 14:13

Make	Isuzu	Model	Traviz
YOM	2023	Odo Meter Reading	34,655
Registration No.	EAI8740	Chassis No.	MHCPHR54DPJ530404
CC	2.5	Transmission	M/T
Fuel Type	Diesel	Type of Body	Utility Vehicle
Colour	White		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	99.3	114	92	92
2	Boot Lid	170.6	155	175	182
3	Roof	84.4	67	87	85/99
4	Left Front Fender	94.8	87	89	109
5	Left Front Door	97.0	110	91	90
6	Center Panel Left	136.0	122	146	140
7	Left Rear Door				
8	Left Back Panel	189.3	152	226	190
9	Right Front Fender	123.0	126	118	125
10	Right Front Door	125.6	118	141	118
11	Center Panel Right	146.0	125	158	155
12	Right Rear Door				
13	Right Back Panel	215.6	237	176	234

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : C
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Ceiling - Grime - Minimal / (R) Front Trim - Grime - Minimal / (L) Front Seat - Cigarette Burns - Burnt Minimal / Rear Seat - Cut, Crack - Medium	Remarks (L) Rear Corner Panel - Repair Traces - Yes / (R) Rear Corner Panel - Repair Traces - Yes / Roof - Repair Traces - Yes / (R) Front Fender, Molding - Scratch - Minimal / (R) Mirror - Scratch - Minimal / (R) Front Door, Molding - Scratch - Minimal / (R) Step, In-panel, Side Spoiler - Scratch - Small / Roof - Dent - Large / (R) Side Gate - Scratch - Small / Rear Bumper, Lamps, Panels - Scratch - Small / Rear Gate - Scratch - Minimal / (L) Side Gate - Scratch - Small / (L) Front Door, Molding - Scratch - Medium / (L) Mirror - Faded(Color, Gloss) - Yes / Antennae - Damaged - Yes / Front Bumper, Grille, Lamps - Scratch - Minimal / (L) Step, In-panel, Side Spoiler - Scratch - Small
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Audio, Radio - Issue - Yes / Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist

Inspector Notes
With Lto plate, with jack, 1key, no warranty booklet and spare tire and tools, scratches on headlights, rear door handle issue