

General Information

Date & Time: 05, Mar, 2025 10:02

Make	Toyota	Model	Wigo
YOM	2024	Mileage	9,146
Registration No.	DBN7594	Chassis No.	MHKAA1BC9PJ008445
CC	1.0	Transmission	CVT
Fuel Type	Gas	Type of Body	Hatchback
Colour	Red Mica Metallic		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	105.6	100	112	105
2	Boot Lid	80.7	71	85	86
3	Roof	86.4	82	89	89/86
4	Left Front Fender	86.7	67	90	103
5	Left Front Door	108.3	104	107	114
6	Center Panel Left				
7	Left Rear Door	91.1	97	95	81
8	Left Back Panel	85.3	83	88	86
9	Right Front Fender	82.3	86	85	76
10	Right Front Door	94.1	100	96	87
11	Center Panel Right				
12	Right Rear Door	91.6	84	91	100
13	Right Back Panel	86.2	88	88	82

Overall Evaluation :

A

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : A	Exterior Evaluation : B
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (L) Front Floor Mat - Worked - Small	Remarks (R) Front Fender, Molding - Dent - Small / Front Bumper, Grille, Lamps - Scratch - Small / (L) Front Fender, Molding - Scratch - Minimal / (L) Step, In-panel, Side Spoiler - Scratch - Small / (L) Front Door, Molding - Scratch - Minimal / Rear Bumper, Lamps, Panels - Scratch - Small / (R) Step, In-panel, Side Spoiler - Scratch - Small
Frame Evaluation : A	Functional Evaluation : C
Remarks Defects not found	Remarks Shift Shock - Function - Weak / Battery - Weak - Yes / Horn - Issue - Yes / Spare Key - Issue - Unexist

Inspector Notes
seek horn due to weak battery/ transmission issue (need to press shift lock to shift to other gear) weak battery issue/ with warranty booklet and LTO plate/ with spare tire jack, and tools/