

General Information

Date & Time: 05, Mar, 2025 08:17

Make	Suzuki	Model	Ertiga
YOM	2023	Mileage	13,388
Registration No.	NOV2546	Chassis No.	MHYNC32S5RJ100160
CC	1.5	Transmission	M/T
Fuel Type	Hybrid	Type of Body	Wagon
Colour	Red		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	87.3	89	83	90
2	Boot Lid	84.3	84	85	84
3	Roof	80.1	78	79	86/78
4	Left Front Fender	81.7	79	80	86
5	Left Front Door	86.1	93	85	80
6	Center Panel Left				
7	Left Rear Door	84.7	83	77	95
8	Left Back Panel	80.3	83	81	77
9	Right Front Fender	74.5	75	76	72
10	Right Front Door	85.5	86	80	91
11	Center Panel Right				
12	Right Rear Door	90.8	95	84	94
13	Right Back Panel	79.3	71	83	85

Overall Evaluation :

B

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : B	Exterior Evaluation : C
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Overall Interior - Animal Hair - Yes	Remarks (L) Rear Door, Molding - Scratch & Dent - Large / Front Bumper, Grille, Lamps - Scratch & Dent - Medium / (R) Rear Door, Molding - Scratch - Small / (R) Step, In-panel, Side Spoiler - Scratch - Small / (R) Front Door, Molding - Scratch - Small / Rear Bumper, Lamps, Panels - Scratch - Medium / Roof - Dent - Small
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Spare Key - Issue - Unexist

Inspector Notes

with warranty booklet and LTO plate/ with spare tire and tools and jack/