

## General Information

Date & Time: 28, Mar, 2025 08:14

<b>Make</b>	Toyota	<b>Model</b>	Vios
<b>YOM</b>	2024	<b>Mileage</b>	25,713
<b>Registration No.</b>	NFR1485	<b>Chassis No.</b>	PA1B18F3XR4244934
<b>CC</b>	1.3	<b>Transmission</b>	CVT
<b>Fuel Type</b>	Gas	<b>Type of Body</b>	Sedan
<b>Colour</b>	Blue		

## Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	108.0	115	99	110
2	Boot Lid	94.3	90	94	99
3	Roof	96.5	90	98	98/100
4	Left Front Fender	96.5	93	107	90
5	Left Front Door	93.8	91	98	92
6	Center Panel Left				
7	Left Rear Door	99.7	103	100	96
8	Left Back Panel	120.5	164	98	99
9	Right Front Fender	97.6	98	98	98
10	Right Front Door	99.1	97	100	101
11	Center Panel Right				
12	Right Rear Door	101.6	101	103	101
13	Right Back Panel	103.4	99	95	116

Overall Evaluation :

**B**

### Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

<b>Interior Evaluation :</b>	<b>B</b>	<b>Exterior Evaluation :</b>	<b>B</b>
<p><b>a</b> : Cut, Fray <b>d</b> : Loose, Deformed <b>k</b> : Animal Hair <b>s</b> : Smell <b>t</b> : Cigarette Burns <b>x</b> : Defective <b>y</b> : Stain</p>		<p><b>A</b> : Scratch <b>AU</b> : Scratch &amp; Dent <b>B</b> : Modified <b>C</b> : Corrosion <b>G</b> : Stone chip <b>P</b> : Faded <b>S</b> : Rust <b>SC</b> : Rust &amp; Corrosion <b>U</b> : Dent <b>X</b> : Defective <b>Y</b> : Crack, Gap</p>	
<p><b>Remarks</b> Ceiling - Grime - Minimal / Rear Seat - Grime - Medium / (L) Front Trim - Grime - Minimal / (L) Front Seat - Grime - Minimal / Console, Switchs, Vents - Worn, Scratch, Cut, Crack - Minimal</p>		<p><b>Remarks</b> (L) Rear Fender - Repair Traces - Yes / (R) Front Fender, Molding - Scratch - Minimal / (R) Front Door, Molding - Scratch - Minimal / (R) Rear Door, Molding - Scratch - Minimal / (R) Rear Fender, Molding - Scratch - Small / Rear Bumper, Lamps, Panels - Dent - Small / Trunk Hood, Rear Gate - Scratch - Minimal / (L) Rear Fender, Molding - Scratch - Minimal / (L) Rear Door, Molding - Scratch - Small / (L) Front Door, Molding - Scratch - Small / (L) Front Fender, Molding - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch - Small / Member (Bolted) - Dent - Yes / Bonnet, Headlight - Scratch - Minimal</p>	
<b>Frame Evaluation :</b>	<b>A</b>	<b>Functional Evaluation :</b>	<b>B</b>
<p><b>Remarks</b> Defects not found</p>		<p><b>Remarks</b> Battery - Weak - Yes</p>	

<b>Inspector Notes</b>
with LTOplate/with warranty booklet/with jack and tools/with spare tire