

General Information

Date & Time: 30, Sep, 2024 11:15

Make	Toyota	Model	Vios
YOM	2023	Mileage	20,981
Registration No.	NHI2724	Chassis No.	PA1B18F31P4204710
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Black		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	109.3	111	103	114
2	Boot Lid	109.3	108	109	111
3	Roof	105.2	111	103	101/106
4	Left Front Fender	103.6	105	106	100
5	Left Front Door	105.6	107	100	110
6	Center Panel Left				
7	Left Rear Door	113.3	121	113	106
8	Left Back Panel	115.6	128	113	106
9	Right Front Fender	99.6	98	101	100
10	Right Front Door	98.0	97	94	103
11	Center Panel Right				
12	Right Rear Door	95.3	91	93	102
13	Right Back Panel	100.1	94	98	108

Overall Evaluation :

A

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : A	Exterior Evaluation : C
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Defects not found	Remarks (L) Rear Fender, Molding - Scratch & Dent - Large / Rear Bumper, Lamps, Panels - Scratch & Dent - Medium / (R) Front Door, Molding - Scratch - Small / (R) Front Fender, Molding - Scratch - Small / Front Bumper, Grille, Lamps - Scratch - Small / Bonnet, Headlight - Scratch - Small / (L) Rear Door, Molding - Scratch & Dent - Minimal / (R) Mirror - Scratch - Minimal
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Reverse Camera - N/A - Yes

Inspector Notes

adhesive marks at the right side front and rear doors and at the side mirror. more light scratches around the exterior. rear seats has molds.