

General Information

Date & Time: 04, Apr, 2025 14:33

Make	Toyota	Model	Avanza
YOM	2024	Mileage	12,994
Registration No.	DBO4879	Chassis No.	MHFAA1BY6P0020486
CC	1.3	Transmission	M/T
Fuel Type	Gas	Type of Body	MPV
Colour	Red Mica Metallic		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	118.6	113	119	124
2	Boot Lid	100.2	92	107	102
3	Roof	117.7	135	132	100/104
4	Left Front Fender	90.1	93	88	89
5	Left Front Door	111.6	105	118	112
6	Center Panel Left				
7	Left Rear Door	120.3	118	102	141
8	Left Back Panel	107.4	104	95	123
9	Right Front Fender	97.0	94	93	105
10	Right Front Door	114.3	122	108	113
11	Center Panel Right				
12	Right Rear Door	111.0	109	103	121
13	Right Back Panel	111.5	117	95	123

Overall Evaluation :

B

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : B	Exterior Evaluation : C
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (L) Front Floor Mat - Missing - Yes / (R) Front Floor Mat - Missing - Yes / Mat Other - Missing - Yes / Ceiling - Cut, Crack - Small	Remarks (R) Mirror - Scratch - Minimal / (R) Rear Door, Molding - Scratch & Dent - Medium / (R) Rear Fender, Molding - Scratch - Small / Rear Bumper, Lamps, Panels - Scratch - Large / (L) Rear Fender, Molding - Scratch - Small / (L) Rear Door, Molding - Scratch - Small / (L) Front Fender, Molding - Scratch - Small / Front Bumper, Grille, Lamps - Scratch & Dent - Large / Member (Bolted) - Dent - Yes / Bonnet, Headlight - Dent - Small
Frame Evaluation : B	Functional Evaluation : A
Remarks Front Cross Member Support - Traces of Bending, or Marks of Panel Repair ? - Yes	Remarks Defects not found

Inspector Notes
with warranty booklet, no jack, incomplete tools, with spare tire, with LTO plate, engine hood issue, all floormat missing