

General Information

Date & Time: 31, Mar, 2025 17:11

Make	Toyota	Model	Avanza
YOM	2024	Mileage	10,931
Registration No.	NHS4911	Chassis No.	MHFAA1BY0R0027274
CC	1.3	Transmission	M/T
Fuel Type	Gas	Type of Body	MPV
Colour	Black		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	115.6	108	109	130
2	Boot Lid	92.5	92	101	85
3	Roof	115.2	124	128	106/103
4	Left Front Fender	100.8	99	108	96
5	Left Front Door	109.3	106	109	113
6	Center Panel Left				
7	Left Rear Door	118.6	112	102	142
8	Left Back Panel	110.3	121	112	98
9	Right Front Fender	103.6	107	104	100
10	Right Front Door	103.6	111	101	99
11	Center Panel Right				
12	Right Rear Door	106.0	115	100	103
13	Right Back Panel	110.0	101	111	118

Overall Evaluation :

B

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : B	Exterior Evaluation : D
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Ceiling - Crinkle - Medium	Remarks Front Bumper, Grille, Lamps - Scratch - Large / (R) Front Door, Molding - Scratch & Dent - Small / (R) Step, In-panel, Side Spoiler - Scratch - Medium / (R) Rear Door, Molding - Scratch & Dent - Small / Rear Bumper, Lamps, Panels - Repair mark - Yes / (R) Rear Fender, Molding - Scratch & Dent - Small / Trunk Hood, Rear Gate - Scratch - Small / (L) Rear Fender, Molding - Scratch - Minimal / (L) Step, In-panel, Side Spoiler - Dent - Small / Front Bumper, Grille, Lamps - Repair mark - Yes / (L) Rear Door, Molding - Scratch & Dent - Small / (L) Front Door, Molding - Scratch - Minimal / (L) Front Fender, Molding - Scratch - Minimal / Roof - Scratch - Large / Bonnet, Headlight - Scratch - Small
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Reverse Camera - N/A - Yes

Inspector Notes

with LTO plate / with jack and spare tire/ no tools/ no warranty booklet/ scratch on tail light/ scratch on wheel cover