

## General Information

Date & Time: 25, Mar, 2025 13:43

<b>Make</b>	Toyota	<b>Model</b>	Vios
<b>YOM</b>	2024	<b>Mileage</b>	11,300
<b>Registration No.</b>	BAG2725	<b>Chassis No.</b>	PA1B18F31R4248631
<b>CC</b>	1.3	<b>Transmission</b>	CVT
<b>Fuel Type</b>	Gas	<b>Type of Body</b>	Sedan
<b>Colour</b>	Red		

## Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	111.0	113	109	111
2	Boot Lid	107.0	104	104	113
3	Roof	106.9	119	103	99/107
4	Left Front Fender	100.7	100	100	103
5	Left Front Door	114.6	122	117	105
6	Center Panel Left				
7	Left Rear Door	111.6	109	116	110
8	Left Back Panel	113.6	121	113	107
9	Right Front Fender	105.0	110	100	105
10	Right Front Door	107.0	100	101	120
11	Center Panel Right				
12	Right Rear Door	112.0	119	104	113
13	Right Back Panel	113.3	109	107	124

## Overall Evaluation :

**A**

### Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

<b>Interior Evaluation :</b> <span style="float: right;"><b>B</b></span>	<b>Exterior Evaluation :</b> <span style="float: right;"><b>A</b></span>
 <p><b>a</b> : Cut, Fray <b>d</b> : Loose, Deformed <b>k</b> : Animal Hair <b>s</b> : Smell <b>t</b> : Cigarette Burns <b>x</b> : Defective <b>y</b> : Stain</p>	 <p><b>A</b> : Scratch <b>AU</b> : Scratch &amp; Dent <b>B</b> : Modified <b>C</b> : Corrosion <b>G</b> : Stone chip <b>P</b> : Faded <b>S</b> : Rust <b>SC</b> : Rust &amp; Corrosion <b>U</b> : Dent <b>X</b> : Defective <b>Y</b> : Crack, Gap</p>
<p><b>Remarks</b> Rear Seat - Grime - Medium / (R) Front Seat - Grime - Medium / (R) Front Trim - Grime - Small / (L) Front Seat - Grime - Medium / (L) Front Trim - Grime - Medium</p>	<p><b>Remarks</b> Defects not found</p>
<b>Frame Evaluation :</b> <span style="float: right;"><b>A</b></span>	<b>Functional Evaluation :</b> <span style="float: right;"><b>A</b></span>
<p><b>Remarks</b> Defects not found</p>	<p><b>Remarks</b> Defects not found</p>

<p><b>Inspector Notes</b></p>	
<p>with LTO plate/with warranty booklet/with tools and jack/with spare tire</p>	