

## General Information

Date & Time: 03, Jun, 2025 11:20

<b>Make</b>	Toyota	<b>Model</b>	Vios
<b>YOM</b>	2025	<b>Odo Meter Reading</b>	772
<b>Registration No.</b>	NJA1941	<b>Chassis No.</b>	PA1B18F32R4280522
<b>CC</b>	1.3	<b>Transmission</b>	CVT
<b>Fuel Type</b>	Gas	<b>Type of Body</b>	Sedan
<b>Colour</b>	Silver		

## Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	<b>116.6</b>	127	104	119
2	Boot Lid	<b>113.0</b>	111	107	121
3	Roof	<b>106.2</b>	105	107	112/101
4	Left Front Fender	<b>98.1</b>	100	98	97
5	Left Front Door	<b>111.6</b>	103	104	128
6	Center Panel Left				
7	Left Rear Door	<b>104.3</b>	106	107	100
8	Left Back Panel	<b>111.3</b>	118	108	108
9	Right Front Fender	<b>106.6</b>	109	101	110
10	Right Front Door	<b>109.0</b>	109	108	110
11	Center Panel Right				
12	Right Rear Door	<b>108.3</b>	103	108	114
13	Right Back Panel	<b>112.6</b>	117	101	120

**Overall Evaluation :**

**A**

**Disclaimer**

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

<b>Interior Evaluation :</b> <span style="color: red; font-weight: bold; font-size: 1.2em;">A</span>	<b>Exterior Evaluation :</b> <span style="color: red; font-weight: bold; font-size: 1.2em;">A</span>
 <p><b>a</b> : Cut, Fray <b>d</b> : Loose, Deformed <b>k</b> : Animal Hair <b>s</b> : Smell <b>t</b> : Cigarette Burns <b>x</b> : Defective <b>y</b> : Stain</p>	 <p><b>A</b> : Scratch <b>AU</b> : Scratch &amp; Dent <b>B</b> : Modified <b>C</b> : Corrosion <b>G</b> : Stone chip <b>P</b> : Faded <b>S</b> : Rust <b>SC</b> : Rust &amp; Corrosion <b>U</b> : Dent <b>X</b> : Defective <b>Y</b> : Crack, Gap</p>
<b>Remarks</b> Defects not found	<b>Remarks</b> Front Bumper, Grille, Lamps - Scratch - Minimal / (R) Rear Fender, Molding - Scratch - Minimal / Trunk Hood, Rear Gate - Scratch - Minimal / (L) Rear Door, Molding - Scratch - Minimal / (L) Front Door, Molding - Scratch - Minimal
<b>Frame Evaluation :</b> <span style="color: red; font-weight: bold; font-size: 1.2em;">A</span>	<b>Functional Evaluation :</b> <span style="color: red; font-weight: bold; font-size: 1.2em;">A</span>
<b>Remarks</b> Defects not found	<b>Remarks</b> Defects not found

<b>Inspector Notes</b>
no LTO plate, with warranty booklet, with jack, no tools, with spare tire, trunk mat missing