

General Information

Date & Time: 04, Apr, 2025 12:49

Make	Toyota	Model	Avanza
YOM	2024	Mileage	19,979
Registration No.	EAG7220	Chassis No.	MHFAA1BY6P0022142
CC	1.3	Transmission	M/T
Fuel Type	Gas	Type of Body	MPV
Colour	Black		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	103.6	105	104	102
2	Boot Lid	90.2	90	97	84
3	Roof	163.5	176	157	139/182
4	Left Front Fender	120.0	107	152	101
5	Left Front Door	114.6	105	117	122
6	Center Panel Left				
7	Left Rear Door	120.6	114	113	135
8	Left Back Panel	114.0	130	108	104
9	Right Front Fender	106.3	103	105	111
10	Right Front Door	112.3	120	111	106
11	Center Panel Right				
12	Right Rear Door	111.3	114	104	116
13	Right Back Panel	122.6	103	138	127

Overall Evaluation :

B

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : B	Exterior Evaluation : D
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Rear Seat - Grime - Medium / Trunk Room - Worn, Scratch, Cut, Crack - Small / Mat Other - Missing - Yes / Ceiling - Grime - Minimal	Remarks (L) Rear Door - Repair Traces - Yes / (R) Rear Door - Repair Traces - Yes / Roof - Repair Traces - Yes / (R) Rear Fender, Molding - Repair mark - Yes / Rear Bumper, Lamps, Panels - Repair mark - Yes / (L) Rear Fender, Molding - Repair mark - Yes / (R) Front Fender, Molding - Scratch - Minimal / (R) Mirror - Scratch - Minimal / (R) Front Door, Molding - Scratch - Small / (R) Rear Door, Molding - Scratch - Medium / Trunk Hood, Rear Gate - Scratch - Small / (L) Rear Door, Molding - Scratch - Small / (L) Front Door, Molding - Scratch - Minimal / (L) Mirror - Scratch - Minimal / (L) Front Fender, Molding - Scratch - Small / Front Bumper, Grille, Lamps - Scratch - Large / Bonnet, Headlight - Scratch - Small / Roof - Repair mark - Yes / Roof - Dent - Large
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Defects not found

Inspector Notes
with LTO plate, with warranty booklet, with jack,incomplete tools,with spare tire,paint splatter on front left door