

General Information

Date & Time: 15, Apr, 2025 12:33

Make	Toyota	Model	Vios
YOM	2023	Mileage	20,692
Registration No.	NIP3689	Chassis No.	PA1B18F33P4225350
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Blue		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	98.1	97	98	100
2	Boot Lid	100.2	88	113	100
3	Roof	88.5	92	88	87/88
4	Left Front Fender	90.5	95	88	89
5	Left Front Door	93.3	93	97	89
6	Center Panel Left				
7	Left Rear Door	94.8	100	88	97
8	Left Back Panel	97.3	105	96	91
9	Right Front Fender	117.7	98	91	165
10	Right Front Door	90.5	89	92	91
11	Center Panel Right				
12	Right Rear Door	87.3	84	88	90
13	Right Back Panel	87.8	84	87	93

Overall Evaluation :

A

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : C	Exterior Evaluation : A
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Rear Seat - Grime - Large / (R) Front Seat - Grime - Small / Dashboard - Traces of Adhesive Tape - Yes / (L) Front Floor Mat - Grime - Minimal / (L) Front Trim - Grime - Medium	Remarks (R) Front Fender - Repair Traces - Yes / Rear Bumper, Lamps, Panels - Scratch - Small / (R) Front Door, Molding - Scratch - Small / (L) Front Door, Molding - Dent - Minimal / (L) Rear Door, Molding - Scratch - Minimal / (R) Front Fender, Molding - Dent - Minimal / (R) Rear Door, Molding - Dent - Minimal / Trunk Hood, Rear Gate - Scratch - Minimal / (L) Rear Fender, Molding - Scratch - Minimal
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist

Inspector Notes

with LTO plate/with spare tire/with warranty booklet/with jack and tools/No reverse camera