

General Information

Date & Time: 23, Apr, 2025 13:28

Make	Toyota	Model	Wigo
YOM	2021	Mileage	48,765
Registration No.	NEL2473	Chassis No.	MHKA4DF5FMJ054412
CC	1.0	Transmission	A/T
Fuel Type	Gas	Type of Body	Hatchback
Colour	Black		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	71.7	71	78	67
2	Boot Lid	91.3	88	97	89
3	Roof	69.6	50	80	84/65
4	Left Front Fender	74.8	68	78	79
5	Left Front Door	81.6	83	85	76
6	Center Panel Left				
7	Left Rear Door	80.8	75	86	81
8	Left Back Panel	79.0	85	75	77
9	Right Front Fender	83.8	88	90	74
10	Right Front Door	75.6	74	77	76
11	Center Panel Right				
12	Right Rear Door	77.1	83	74	75
13	Right Back Panel	83.1	79	82	89

Overall Evaluation :

D

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : D	Exterior Evaluation : E
The diagram shows the interior of a vehicle from a top-down perspective. Inspection points are numbered 1 through 9. Codes are placed around the seats and floor: Y3 on both front and rear seat sides, D4 at the bottom center, and X1 on the driver's side headrest area.	The diagram shows the exterior of a vehicle from three perspectives: front, left side, and right side. Inspection points are numbered 1 through 17. Codes are placed on various body panels: A1, A2, AU2, AU3, B1, C1, G1, P1, S1, SC1, U1, X1, Y1 on the front; A1, A2, AU2, AU3, B1, C1, G1, P1, S1, SC1, U1, X1, Y1 on the left side; and A1, A2, AU2, AU3, B1, C1, G1, P1, S1, SC1, U1, X1, Y1 on the right side.
a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (R) Front Seat - Grime - Medium / Rear Seat - Grime - Medium / (L) Front Floor Mat - Worked - Large / (L) Front Trim - Grime - Medium / (L) Rear Trim - Grime - Medium / (R) Front Trim - Grime - Medium / (R) Rear Trim - Grime - Medium / Trunk Room - Loose, Deformed - Large / (R) Front Floor Mat - Missing - Yes	Remarks (R) Step, In-panel, Side Spoiler - Scratch & Dent - Large / (R) Rear Door, Molding - Scratch & Dent - Medium / (L) Front Door, Molding - Dent - Medium / Front Bumper, Grille, Lamps - Crack, Gap - Large / Rear Bumper, Lamps, Panels - Crack, Gap - Medium / Trunk Hood, Rear Gate - Scratch - Small / (L) Rear Fender, Molding - Scratch & Dent - Small / (L) Rear Door, Molding - Scratch - Medium / (L) Step, In-panel, Side Spoiler - Scratch & Dent - Medium / (R) Front Door, Molding - Scratch - Small / (R) Mirror - Scratch - Minimal / (R) Front Fender, Molding - Scratch - Minimal / Bonnet, Headlight - Scratch - Small / (R) Rear Fender, Molding - Scratch - Small / (L) Front Fender, Molding - Scratch - Minimal / (L) Mirror - Scratch - Small / Roof - Scratch & Dent - Small
Frame Evaluation : C	Functional Evaluation : D
Remarks Front Cross Member Support - Traces of Bending, or Marks of Panel Repair ? - Yes / Right Front Inside Panel (Front Side) - Traces of Bending, or Marks of Panel Repair ? - Yes	Remarks Warning Lamps - Issue - Yes / Door Lock - Issue - Yes / Shift Shock - Function - Weak / Battery - Weak - Yes / Head Light, High Beam - Issue - Yes / Lamps (Brake, Tail, Fog) - Issue - Yes / Spare Key - Issue - Unexist

Inspector Notes

with LTO plate, with warranty booklet, no jack, no tools, with spare tire, dome light issue, headlight issue , cracked tail light, possible flooding