

General Information

Date & Time: 28, Apr, 2025 15:45

Make	Toyota	Model	Vios
YOM	2024	Mileage	22,596
Registration No.	CAZ8993	Chassis No.	PA1B18F39P4233162
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Green		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	95.3	92	94	100
2	Boot Lid	94.5	93	94	97
3	Roof	86.7	85	89	84/90
4	Left Front Fender	88.5	98	80	88
5	Left Front Door	89.3	86	91	91
6	Center Panel Left				
7	Left Rear Door	88.5	98	87	82
8	Left Back Panel	96.1	109	94	86
9	Right Front Fender	88.1	91	86	87
10	Right Front Door	94.3	96	94	93
11	Center Panel Right				
12	Right Rear Door	92.5	88	92	98
13	Right Back Panel	87.3	84	85	94

Overall Evaluation :

B

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : B	Exterior Evaluation : C
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (R) Front Seat - Grime - Medium / (L) Front Seat - Grime - Medium / Rear Seat - Grime - Medium / (R) Front Trim - Grime - Minimal / (L) Front Trim - Grime - Minimal / Ceiling - Grime - Small	Remarks (R) Mirror - Scratch - Small / (R) Front Door, Molding - Scratch & Dent - Large / (R) Rear Door, Molding - Scratch - Small / Rear Bumper, Lamps, Panels - Scratch - Large / Trunk Hood, Rear Gate - Scratch & Dent - Small / (L) Rear Door, Molding - Scratch - Small / (L) Mirror - Scratch - Minimal / (L) Front Door, Molding - Scratch - Minimal / Member (Bolted) - Dent - Yes / Front Bumper, Grille, Lamps - Scratch & Dent - Medium
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Reverse Camera - N/A - Yes

Inspector Notes
with warranty booklet, with jack, no tools, with spare tire, with LTO plate