


General Information

Date & Time: 28, Apr, 2025 15:42

Make	Toyota	Model	Vios
YOM	2024	Mileage	8,198
Registration No.	NHR8509	Chassis No.	PA1B18F35P4231232
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Green		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	100.4	96	102	103
2	Boot Lid	96.1	93	97	99
3	Roof	90.8	99	90	82/92
4	Left Front Fender	90.2	91	91	89
5	Left Front Door	89.5	90	89	90
6	Center Panel Left				
7	Left Rear Door	90.2	91	92	88
8	Left Back Panel	96.3	98	98	93
9	Right Front Fender	94.3	96	93	94
10	Right Front Door	95.2	99	90	97
11	Center Panel Right				
12	Right Rear Door	97.5	93	91	109
13	Right Back Panel	97.3	97	95	100

Overall Evaluation :

B

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : B	Exterior Evaluation : C
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Dashboard - Traces of Adhesive Tape - Yes / (R) Front Seat - Grime - Small / Rear Seat - Grime - Small / (L) Front Seat - Grime - Minimal / (L) Front Trim - Grime - Medium / Ceiling - Grime - Minimal / (R) Front Trim - Grime - Minimal	Remarks Rear Bumper, Lamps, Panels - Scratch - Medium / (L) Rear Door, Molding - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch & Dent - Large / (R) Mirror - Scratch - Minimal / (R) Front Door, Molding - Scratch - Medium / (R) Rear Door, Molding - Dent - Medium / (R) Rear Fender, Molding - Scratch - Minimal / (L) Rear Fender, Molding - Scratch - Minimal / (L) Front Fender, Molding - Scratch - Minimal
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist

Inspector Notes
with LTO plate/with spare tire/with jack /No tools/with warranty booklet/No reverse camera