


General Information

Date & Time: 05, Oct, 2024 11:17

Make	Toyota	Model	Vios
YOM	2023	Mileage	13,383
Registration No.	BAF4678	Chassis No.	PA1B18F31P4225251
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	BLACKISH RED MICA		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	112.6	116	107	115
2	Boot Lid	114.0	106	116	120
3	Roof	109.2	109	105	115/108
4	Left Front Fender	108.3	107	111	107
5	Left Front Door	103.2	100	99	111
6	Center Panel Left				
7	Left Rear Door	112.6	122	112	104
8	Left Back Panel	112.6	117	107	114
9	Right Front Fender	105.6	106	100	111
10	Right Front Door	106.0	108	101	109
11	Center Panel Right				
12	Right Rear Door	110.0	105	108	117
13	Right Back Panel	110.0	104	106	120

Overall Evaluation :

A

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : B	Exterior Evaluation : B
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (R) Front Seat - Grime - Minimal / Trunk Room - Loose, Deformed, Grime - Medium	Remarks Bonnet, Headlight - Scratch - Small / Front Bumper, Grille, Lamps - Scratch - Minimal / (L) Front Door, Molding - Scratch - Small / (L) Rear Door, Molding - Scratch - Minimal / (L) Rear Fender, Molding - Scratch - Small / Trunk Hood, Rear Gate - Scratch - Small / (R) Rear Fender, Molding - Scratch - Small / (R) Front Door, Molding - Scratch - Small / (R) Mirror - Scratch - Minimal
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Reverse Camera - N/A - Yes

Inspector Notes
more light scratches around the exterior.