

General Information

Date & Time: 25, Apr, 2025 15:10

Make	Toyota	Model	Vios
YOM	2024	Mileage	6,667
Registration No.	NHM1792	Chassis No.	PA1B18F3XP4234109
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	White		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	97.6	101	88	104
2	Boot Lid	120.3	117	124	120
3	Roof	92.0	92	91	93/92
4	Left Front Fender	94.0	96	91	95
5	Left Front Door	87.3	90	88	84
6	Center Panel Left				
7	Left Rear Door	85.9	89	87	81
8	Left Back Panel	98.3	108	94	94
9	Right Front Fender	101.6	98	100	107
10	Right Front Door	97.3	97	97	99
11	Center Panel Right				
12	Right Rear Door	97.1	94	97	101
13	Right Back Panel	100.4	91	95	116

Overall Evaluation :

B

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : A	Exterior Evaluation : D
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (L) Front Floor Mat - Worked - Small	Remarks (L) Front Door, Molding - Scratch & Dent - Medium / (L) Rear Door, Molding - Scratch & Dent - Medium / (L) Front Fender, Molding - Scratch - Large / Front Bumper, Grille, Lamps - Scratch & Dent - Medium / (R) Rear Door, Molding - Dent - Small / (R) Front Door, Molding - Dent - Small / Rear Bumper, Lamps, Panels - Scratch - Large / (L) Rear Fender, Molding - Scratch - Minimal / (L) Front Wheel, Cover - Scratch, Corrosion - Small / (L) Rear Wheel, Cover - Scratch, Corrosion - Small / (R) Front Wheel, Cover - Scratch, Corrosion - Small / (R) Rear Wheel, Cover - Scratch, Corrosion - Small / (R) Rear Fender, Molding - Scratch - Small
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Reverse Camera - N/A - Yes

Inspector Notes
with warranty booklet and LTO plate/ no jack and tools/