

General Information

Date & Time: 23, Apr, 2025 14:18

Make	Toyota	Model	Vios
YOM	2024	Mileage	7,256
Registration No.	NHH3794	Chassis No.	PA1B18F30R4255201
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Black		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	101.6	100	102	103
2	Boot Lid	91.0	89	90	94
3	Roof	93.7	95	93	88/100
4	Left Front Fender	86.3	90	88	81
5	Left Front Door	90.2	93	91	88
6	Center Panel Left				
7	Left Rear Door	94.9	106	95	84
8	Left Back Panel	99.0	94	98	105
9	Right Front Fender	85.2	87	82	87
10	Right Front Door	88.8	91	87	89
11	Center Panel Right				
12	Right Rear Door	89.6	82	90	97
13	Right Back Panel	94.8	92	89	103

Overall Evaluation :

A

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation :	A	Exterior Evaluation :	C
The diagram shows the interior of a vehicle from above. Numbered areas are: 1 (Frontal air vents), 2 (Front passenger headrest area), 3 (Center console gear shift area), 4 (Front driver's seat headrest area), 5 (Front driver's seat backrest area), 6 (Side sills), 7 (Rear bench seat backrest area), 8 (Rear cargo area floor), 9 (Front passenger seat backrest area), and 10 (Side sills).		The diagram shows the exterior of a vehicle from three perspectives: front, side, and rear. Numbered areas are: 1 (Front left fender), 2 (Front right fender), 3 (Front bumper/grille), 4 (Front left door), 5 (Front right door), 6 (Front left wheel arch), 7 (Front right wheel arch), 8 (Front left door lower panel), 9 (Front right door lower panel), 10 (Front left wheel), 11 (Front right wheel), 12 (Front hood), 13 (Front trunk), 14 (Rear bumper), 15 (Rear wheel). Defect codes are placed near specific areas: AU3 (Front right wheel), A2 (Front left door, Front right door, Rear bumper), U2 (Front right door), B (Front right door), C (Front right door), G (Front right door), P (Front right door), S (Front right door), SC (Front right door), X (Front right door), Y (Front right door).	
a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain		A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap	
Remarks Defects not found		Remarks (R) Front Fender, Molding - Dent - Small / (L) Rear Fender, Molding - Scratch - Medium / (L) Front Door, Molding - Scratch - Small / (L) Rear Door, Molding - Scratch - Small / Front Bumper, Grille, Lamps - Scratch & Dent - Medium / (R) Front Door, Molding - Scratch - Small / (R) Rear Door, Molding - Scratch - Small / Rear Bumper, Lamps, Panels - Scratch - Small	
Frame Evaluation :	A	Functional Evaluation :	A
Remarks Defects not found		Remarks Defects not found	

Inspector Notes

no warranty booklet/ no spare tire/ no tools and jack/ with LTO plate