

General Information

Date & Time: 29, Apr, 2025 08:13

Make	Toyota	Model	Vios
YOM	2020	Mileage	73,924
Registration No.	DAZ2436	Chassis No.	PA1B18F32K4107407
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Black		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	94.9	89	102	94
2	Boot Lid	101.6	93	121	91
3	Roof	78.2	83	72	76/83
4	Left Front Fender	83.3	81	82	87
5	Left Front Door	88.0	93	91	80
6	Center Panel Left				
7	Left Rear Door	88.0	86	87	91
8	Left Back Panel	96.4	103	93	94
9	Right Front Fender	82.2	81	81	85
10	Right Front Door	82.9	80	86	83
11	Center Panel Right				
12	Right Rear Door	81.1	77	82	85
13	Right Back Panel	87.4	81	85	97

Overall Evaluation :

B

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : B		Exterior Evaluation : C	
			
a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain		A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap	
Remarks (L) Front Trim - Grime - Medium / (R) Front Trim - Grime - Small / Ceiling - Grime - Small		Remarks Member (Bolted) - Dent - Yes / (R) Rear Fender, Molding - Dent - Small / (R) Rear Door, Molding - Scratch & Dent - Large / (R) Front Door, Molding - Scratch & Dent - Small / Rear Bumper, Lamps, Panels - Scratch & Dent - Medium / Trunk Hood, Rear Gate - Dent - Small / (L) Rear Fender, Molding - Scratch & Dent - Small / (L) Step, In-panel, Side Spoiler - Scratch & Dent - Small / (L) Front Door, Molding - Dent - Minimal / Front Bumper, Grille, Lamps - Scratch - Medium / (R) Front Fender, Molding - Crack, Gap - Medium	
Frame Evaluation : A		Functional Evaluation : A	
Remarks Defects not found		Remarks Reverse Camera - N/A - Yes / Horn - Issue - Yes / Spare Key - Issue - Unexist	

Inspector Notes

with LTO plate/with spare tire/No jack and tools/No reverse camera/No warranty booklet/plate light issue/No horn