


## General Information

Date & Time: 28, Apr, 2025 14:48

<b>Make</b>	Ford	<b>Model</b>	Everest
<b>YOM</b>	2018	<b>Mileage</b>	184,327
<b>Registration No.</b>	NBR8310	<b>Chassis No.</b>	MNCAXXMAWAJS21882
<b>CC</b>	2.2	<b>Transmission</b>	A/T
<b>Fuel Type</b>	Diesel	<b>Type of Body</b>	Wagon
<b>Colour</b>	Silver		

## Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	109.6	109	109	111
2	Boot Lid	99.8	96	101	102
3	Roof	110.5	115	106	111/110
4	Left Front Fender	110.0	115	108	107
5	Left Front Door	103.3	102	100	108
6	Center Panel Left				
7	Left Rear Door	104.1	115	100	98
8	Left Back Panel	112.6	116	109	113
9	Right Front Fender	108.6	105	114	107
10	Right Front Door	110.3	113	107	111
11	Center Panel Right				
12	Right Rear Door	106.7	99	105	116
13	Right Back Panel	114.6	114	113	117

## Overall Evaluation :

**C**

### Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

<b>Interior Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">C</span>	<b>Exterior Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">C</span>
<p><b>a</b> : Cut, Fray <b>d</b> : Loose, Deformed <b>k</b> : Animal Hair <b>s</b> : Smell <b>t</b> : Cigarette Burns <b>x</b> : Defective <b>y</b> : Stain</p>	<p><b>A</b> : Scratch <b>AU</b> : Scratch &amp; Dent <b>B</b> : Modified <b>C</b> : Corrosion <b>G</b> : Stone chip <b>P</b> : Faded <b>S</b> : Rust <b>SC</b> : Rust &amp; Corrosion <b>U</b> : Dent <b>X</b> : Defective <b>Y</b> : Crack, Gap</p>
<p><b>Remarks</b>  (R) Rear Trim - Grime - Medium / Sunvisor, Sunglass Holder - Grime - Medium / Overall Interior - Smell - Yes / (L) Front Floor Mat - Grime - Small / (R) Front Floor Mat - Grime - Small / Mat Other - Grime - Small / Ceiling - Grime - Large</p>	<p><b>Remarks</b>  (L) Front Fender - Repair Traces - Yes / (L) Front Fender, Molding - Scratch &amp; Dent - Small / Front Bumper, Grille, Lamps - Scratch - Medium / (R) Front Fender, Molding - Scratch - Small / (R) Rear Door, Molding - Scratch &amp; Dent - Small / (R) Mirror - Scratch - Minimal / Rear Bumper, Lamps, Panels - Scratch &amp; Dent - Large / (L) Front Door, Molding - Scratch &amp; Dent - Small / (L) Rear Door, Molding - Scratch - Small</p>
<b>Frame Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">A</span>	<b>Functional Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">E</span>
<p><b>Remarks</b>  Defects not found</p>	<p><b>Remarks</b>  Retractable Mirror - Issue - Yes / Warning Lamps - Issue - Yes / Panel, Meter - Issue - Yes / Power Window (each) - Stuck, Gap - Yes / Air Conditioner - Function - Weak / Audio, Radio - Issue - Yes / Reverse Camera - N/A - Yes / Turn Signal, Hazard Flasher - Issue - Yes / Head Light, High Beam - Issue - Yes / Lamps (Brake, Tail, Fog) - Issue - Yes / Wiper - Function - Weak / Spare Key - Issue - Unexist</p>

<p><b>Inspector Notes</b></p>
<p>possible flooding. Instrument panel issue. Check engine, ABS light, airbag issue. with warranty booklet, spare tire, jack and tools. 1 key. with LTO plate.</p>