

General Information

Date & Time: 30, Apr, 2025 08:19

Make	Mitsubishi	Model	Montero SPT
YOM	2018	Mileage	70,900
Registration No.	NEC9362	Chassis No.	MMBGUKR10JH021052
CC	2.5	Transmission	A/T
Fuel Type	Diesel	Type of Body	SUV
Colour	Black		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	284.3	272	333	248
2	Boot Lid	154.0	140	195	127
3	Roof	80.8	84	77	85/77
4	Left Front Fender	312.3	235	186	516
5	Left Front Door	141.6	157	133	135
6	Center Panel Left				
7	Left Rear Door	139.0	172	122	123
8	Left Back Panel	156.3	178	132	159
9	Right Front Fender	168.3	163	172	170
10	Right Front Door	402.3	597	397	213
11	Center Panel Right				
12	Right Rear Door	436.0	313	284	711
13	Right Back Panel	147.3	153	136	153

Overall Evaluation :

D

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : C	Exterior Evaluation : E
a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (R) Front Trim - Grime - Medium / Rear Seat - Grime - Small / (L) Front Trim - Grime - Medium / (L) Front Floor Mat - Grime - Small / (L) Rear Trim - Grime - Small / (R) Rear Trim - Grime - Small / (L) Front Seat - Grime - Minimal / Knobs - Worn, Peel, Crack - Small / (R) Front Seat - Grime - Minimal / Trunk Room - Worn, Scratch, Cut, Crack - Minimal	Remarks (R) Front Door - Repair Traces - Yes / (R) Front Fender - Repair Traces - Yes / Bonnet - Repair Traces - Yes / (L) Front Fender - Repair Traces - Yes / (L) Front Door - Repair Traces - Yes / (L) Rear Door - Repair Traces - Yes / (L) Rear Fender - Repair Traces - Yes / Trunk Hood, Rear Gate - Repair Traces - Yes / (R) Rear Fender - Repair Traces - Yes / (R) Rear Door - Repair Traces - Yes / Roof - Repair Traces - Yes / (R) Front Door, Molding - Repair mark - Yes / (R) Rear Door, Molding - Repair mark - Yes / Front Bumper, Grille, Lamps - Crack, Gap - Large / (R) Front Fender, Molding - Repair mark - Yes / (R) Rear Door, Molding - Dent - Small / (R) Front Door, Molding - Scratch - Small / Rear Bumper, Lamps, Panels - Scratch & Dent - Medium / Trunk Hood, Rear Gate - Scratch - Small / (L) Rear Fender, Molding - Scratch - Medium / (L) Front Door, Molding - Scratch & Dent - Medium / (L) Rear Door, Molding - Scratch - Small / (L) Front Door, Molding - Repair mark - Yes / (L) Front Fender, Molding - Scratch - Minimal / (R) Rear Fender, Molding - Scratch - Medium / Roof - Dent - Small / Bonnet, Headlight - Scratch - Small / (R) Step, In-panel, Side Spoiler - Crack, Gap - Medium
Frame Evaluation : A	Functional Evaluation : D
Remarks Defects not found	Remarks Warning Lamps - Issue - Yes / Shift Shock - Function - Weak / Audio, Radio - Issue - Yes / Reverse Camera - N/A - Yes / Parking Brake - Function - Weak / Brake Pedal - Function - Weak / Spare Key - Issue - Unexist

Inspector Notes

with LTO plate/with spare tire/No jack and incomplete tools/No warranty booklet/reverse camera not working/plate light issue/issue parking brake /missing head unit/