


## General Information

Date & Time: 28, Apr, 2025 15:56

<b>Make</b>	Mitsubishi	<b>Model</b>	Mirage
<b>YOM</b>	2023	<b>Mileage</b>	20,363
<b>Registration No.</b>	DBJ2229	<b>Chassis No.</b>	PAEA13TJPPA008295
<b>CC</b>	1.2	<b>Transmission</b>	A/T
<b>Fuel Type</b>	Gas	<b>Type of Body</b>	Sedan
<b>Colour</b>	Silver		

## Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	121.3	123	119	122
2	Boot Lid	111.6	108	119	108
3	Roof	106.0	104	110	104/106
4	Left Front Fender	114.3	116	114	113
5	Left Front Door	108.6	108	108	110
6	Center Panel Left				
7	Left Rear Door	101.1	106	102	95
8	Left Back Panel	107.3	110	108	104
9	Right Front Fender	112.3	108	111	118
10	Right Front Door	108.3	112	103	110
11	Center Panel Right				
12	Right Rear Door	104.3	103	102	108
13	Right Back Panel	109.0	107	107	113

Overall Evaluation :

**B**

### Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

<b>Interior Evaluation :</b> <span style="float: right;"><b>B</b></span>	<b>Exterior Evaluation :</b> <span style="float: right;"><b>C</b></span>
<p><b>a</b> : Cut, Fray <b>d</b> : Loose, Deformed <b>k</b> : Animal Hair <b>s</b> : Smell <b>t</b> : Cigarette Burns <b>x</b> : Defective <b>y</b> : Stain</p>	<p><b>A</b> : Scratch <b>AU</b> : Scratch &amp; Dent <b>B</b> : Modified <b>C</b> : Corrosion <b>G</b> : Stone chip <b>P</b> : Faded <b>S</b> : Rust <b>SC</b> : Rust &amp; Corrosion <b>U</b> : Dent <b>X</b> : Defective <b>Y</b> : Crack, Gap</p>
<p><b>Remarks</b>          Ceiling - Grime - Small / (R) Front Seat - Grime - Medium / (R) Front Floor Mat - Grime - Medium / (L) Front Seat - Grime - Small</p>	<p><b>Remarks</b>          Rear Bumper, Lamps, Panels - Scratch &amp; Dent - Large / (R) Mirror - Scratch - Minimal / (L) Rear Fender, Molding - Dent - Small / (L) Front Fender, Molding - Dent - Small / (R) Front Fender, Molding - Scratch - Small / Trunk Hood, Rear Gate - Scratch - Minimal / (L) Rear Door, Molding - Scratch &amp; Dent - Minimal</p>
<b>Frame Evaluation :</b> <span style="float: right;"><b>A</b></span>	<b>Functional Evaluation :</b> <span style="float: right;"><b>A</b></span>
<p><b>Remarks</b>          Defects not found</p>	<p><b>Remarks</b>          Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist</p>

<p><b>Inspector Notes</b></p>
<p>With warranty booklet and jack. Without spare tire, tools and seat cover. 1 key. With LTO plate.</p>