

## General Information

Date & Time: 28, Apr, 2025 16:33

<b>Make</b>	Ford	<b>Model</b>	Ranger
<b>YOM</b>	2017	<b>Mileage</b>	99,061
<b>Registration No.</b>	FAB4234	<b>Chassis No.</b>	MNCLMFF80HW689771
<b>CC</b>	2.2	<b>Transmission</b>	A/T
<b>Fuel Type</b>	Diesel	<b>Type of Body</b>	Pickup
<b>Colour</b>	White		

## Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	95.8	84	106	97
2	Boot Lid	162.0	225	136	125
3	Roof	85.4	83	78	89/92
4	Left Front Fender	141.6	164	115	146
5	Left Front Door	143.0	185	118	126
6	Center Panel Left				
7	Left Rear Door	111.6	123	105	107
8	Left Back Panel	113.0	99	103	137
9	Right Front Fender	93.4	90	95	96
10	Right Front Door	100.2	97	100	104
11	Center Panel Right				
12	Right Rear Door	99.4	94	100	105
13	Right Back Panel	120.0	106	101	153

## Overall Evaluation :

**D**

### Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

<b>Interior Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">C</span>	<b>Exterior Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">E</span>
<p><b>a</b> : Cut, Fray <b>d</b> : Loose, Deformed <b>k</b> : Animal Hair <b>s</b> : Smell <b>t</b> : Cigarette Burns <b>x</b> : Defective <b>y</b> : Stain</p>	<p><b>A</b> : Scratch <b>AU</b> : Scratch &amp; Dent <b>B</b> : Modified <b>C</b> : Corrosion <b>G</b> : Stone chip <b>P</b> : Faded <b>S</b> : Rust <b>SC</b> : Rust &amp; Corrosion <b>U</b> : Dent <b>X</b> : Defective <b>Y</b> : Crack, Gap</p>
<p><b>Remarks</b> (R) Front Floor Mat - Grime - Small / (R) Front Seat - Worn - Yes / Mat Other - Grime - Medium / (L) Front Seat - Worn - Yes / (L) Front Floor Mat - Worked - Small / Ceiling - Grime - Large</p>	<p><b>Remarks</b> (R) Step - Repair Traces - Yes / (L) Front Door - Repair Traces - Yes / (R) Front Door, Molding - Scratch &amp; Dent - Large / (R) Side Gate - Scratch - Large / Rear Gate - Scratch &amp; Dent - Large / Rear Bumper, Lamps, Panels - Scratch &amp; Dent - Large / (L) Side Gate - Repair mark - Yes / (L) Mirror - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch - Large / (R) Mirror - Crack - Cracks / Roof - Scratch - Small</p>
<b>Frame Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">A</span>	<b>Functional Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">C</span>
<p><b>Remarks</b> Defects not found</p>	<p><b>Remarks</b> Power Window (each) - Stuck, Gap - Yes / Reverse Camera - N/A - Yes / Lamps (Brake, Tail, Fog) - Issue - Yes / Spare Key - Issue - Unexist</p>

## Inspector Notes

With warranty booklet and spare tire. Without jack and tools. 1 key. With LTO plate. Damaged tail light.