


General Information

Date & Time: 02, May, 2025 10:35

Make	Subaru	Model	Forester
YOM	2018	Mileage	69,017
Registration No.	NAX7228	Chassis No.	JF1SJ5LC5JG391721
CC	2.0	Transmission	A/T
Fuel Type	Gas	Type of Body	Wagon
Colour	Pearl White		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	202.6	178	238	192
2	Boot Lid	178.6	169	184	183
3	Roof	182.5	167	156	215/192
4	Left Front Fender	208.6	212	211	203
5	Left Front Door	191.3	196	181	197
6	Center Panel Left				
7	Left Rear Door	189.6	194	192	183
8	Left Back Panel	182.3	199	176	172
9	Right Front Fender	192.6	202	204	172
10	Right Front Door	174.6	168	174	182
11	Center Panel Right				
12	Right Rear Door	171.0	171	169	173
13	Right Back Panel	194.6	187	188	209

Overall Evaluation :

A

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation :	B	Exterior Evaluation :	B
<p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>		<p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>	
<p>Remarks Ceiling - Grime - Medium / (L) Front Floor Mat - Worked - Small</p>		<p>Remarks (R) Front Door - Repair Traces - Yes / (R) Step - Repair Traces - Yes / (R) Front Fender - Repair Traces - Yes / Bonnet - Repair Traces - Yes / (L) Front Fender - Repair Traces - Yes / (L) Front Door - Repair Traces - Yes / (L) Step - Repair Traces - Yes / (L) Rear Door - Repair Traces - Yes / (L) Rear Fender - Repair Traces - Yes / Trunk Hood, Rear Gate - Repair Traces - Yes / (R) Rear Fender - Repair Traces - Yes / (R) Rear Door - Repair Traces - Yes / Roof - Repair Traces - Yes / (R) Front Door, Molding - Scratch - Small / (L) Front Door, Molding - Scratch - Small / (R) Step, In-panel, Side Spoiler - Scratch - Small / Rear Bumper, Lamps, Panels - Scratch - Medium / (L) Front Fender, Molding - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch - Minimal</p>	
Frame Evaluation :	A	Functional Evaluation :	A
<p>Remarks Defects not found</p>		<p>Remarks Turn Signal, Hazard Flasher - Issue - Yes / Spare Key - Issue - Unexist</p>	

Inspector Notes

When running high speed, the underchassis occurs a rattle noise. Audio display issue. with warranty booklet and spare tire. Without jack and tools. 1 key. Power tailgate issue. With LTO plate.