

## General Information

Date & Time: 02, May, 2025 10:14

<b>Make</b>	Honda	<b>Model</b>	City
<b>YOM</b>	2021	<b>Mileage</b>	59,719
<b>Registration No.</b>	NGN3672	<b>Chassis No.</b>	MRHGN2620MT060145
<b>CC</b>	1.5	<b>Transmission</b>	A/T
<b>Fuel Type</b>	Gas	<b>Type of Body</b>	Sedan
<b>Colour</b>	White		

## Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	<b>123.0</b>	126	106	137
2	Boot Lid	<b>117.0</b>	111	123	117
3	Roof	<b>102.7</b>	105	103	100/103
4	Left Front Fender	<b>105.0</b>	98	108	109
5	Left Front Door	<b>112.3</b>	114	110	113
6	Center Panel Left				
7	Left Rear Door	<b>112.0</b>	123	107	106
8	Left Back Panel	<b>111.3</b>	112	115	107
9	Right Front Fender	<b>144.3</b>	129	135	169
10	Right Front Door	<b>112.6</b>	116	111	111
11	Center Panel Right				
12	Right Rear Door	<b>111.6</b>	108	110	117
13	Right Back Panel	<b>121.3</b>	124	120	120

Overall Evaluation :

**B**

### Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

<b>Interior Evaluation :</b> <span style="float: right;"><b>B</b></span>	<b>Exterior Evaluation :</b> <span style="float: right;"><b>D</b></span>
 <p><b>a</b> : Cut, Fray <b>d</b> : Loose, Deformed <b>k</b> : Animal Hair <b>s</b> : Smell <b>t</b> : Cigarette Burns <b>x</b> : Defective <b>y</b> : Stain</p>	 <p><b>A</b> : Scratch <b>AU</b> : Scratch &amp; Dent <b>B</b> : Modified <b>C</b> : Corrosion <b>G</b> : Stone chip <b>P</b> : Faded <b>S</b> : Rust <b>SC</b> : Rust &amp; Corrosion <b>U</b> : Dent <b>X</b> : Defective <b>Y</b> : Crack, Gap</p>
<b>Remarks</b> Ceiling - Grime - Medium	<b>Remarks</b> (R) Front Door, Molding - Repair mark - Yes / (R) Front Door, Molding - Scratch & Dent - Small / (R) Rear Door, Molding - Scratch - Large / (R) Rear Fender, Molding - Scratch - Small / Rear Bumper, Lamps, Panels - Scratch - Medium / (L) Front Door, Molding - Scratch & Dent - Small / (L) Front Door, Molding - Repair mark - Yes / (L) Mirror - Scratch - Small / (L) Front Fender, Molding - Scratch - Small / (L) Rear Fender, Molding - Scratch - Small / (L) Rear Door, Molding - Scratch - Medium / Front Bumper, Grille, Lamps - Scratch & Dent - Medium / Bonnet, Headlight - Scratch & Dent - Small / (R) Front Fender, Molding - Scratch - Minimal
<b>Frame Evaluation :</b> <span style="float: right;"><b>A</b></span>	<b>Functional Evaluation :</b> <span style="float: right;"><b>A</b></span>
<b>Remarks</b> Defects not found	<b>Remarks</b> Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist

<b>Inspector Notes</b>
With warranty booklet, spare tire, jack and seat cover. Without tools. 1 key. With LTO plate. Original matting missing.