

General Information

Date & Time: 14, Oct, 2024 19:21

Make	Toyota	Model	Vios
YOM	2023	Mileage	21,650
Registration No.	DBB5967	Chassis No.	PA1B18F35P4205746
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Red		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	105.3	102	105	109
2	Boot Lid	114.0	109	113	120
3	Roof	104.5	104	104	107/103
4	Left Front Fender	387.0	214	813	134
5	Left Front Door	96.5	100	93	96
6	Center Panel Left				
7	Left Rear Door	101.9	106	102	98
8	Left Back Panel	105.2	110	99	107
9	Right Front Fender	173.0	139	178	202
10	Right Front Door	96.1	99	89	101
11	Center Panel Right				
12	Right Rear Door	105.3	101	100	115
13	Right Back Panel	107.3	100	109	113

Overall Evaluation :

A

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : B	Exterior Evaluation : B
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Sunvisor, Sunglass Holder - Grime - Small / Overall Interior - Animal Hair - Yes	Remarks (R) Front Fender - Repair Traces - Yes / (L) Front Fender - Repair Traces - Yes / (L) Front Fender, Molding - Scratch - Small / (L) Front Door, Molding - Scratch - Minimal / (L) Rear Fender, Molding - Scratch - Small / Rear Bumper, Lamps, Panels - Scratch - Small / (R) Rear Fender, Molding - Scratch - Small / (R) Front Door, Molding - Scratch & Dent - Minimal / (R) Front Fender, Molding - Scratch - Small / Front Bumper, Grille, Lamps - Scratch - Minimal
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist

Inspector Notes
more light scratches around the exterior. low washer fluid.