

## General Information

Date & Time: 29, May, 2025 14:04

<b>Make</b>	Suzuki	<b>Model</b>	Carry
<b>YOM</b>	2024	<b>Odo Meter Reading</b>	11,409
<b>Registration No.</b>	NKB3560	<b>Chassis No.</b>	MHYDC61T1SJ210023
<b>CC</b>	1.5	<b>Transmission</b>	M/T
<b>Fuel Type</b>	Gas	<b>Type of Body</b>	Van
<b>Colour</b>	White		

## Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	324.6	702	133	139
2	Boot Lid	205.6	212	206	199
3	Roof	100.2	112	101	92/96
4	Left Front Fender	115.6	114	118	115
5	Left Front Door	111.3	105	111	118
6	Center Panel Left	111.3	121	110	103
7	Left Rear Door				
8	Left Back Panel	179.6	162	194	183
9	Right Front Fender	116.6	112	115	123
10	Right Front Door	100.8	103	103	97
11	Center Panel Right	113.0	115	127	97
12	Right Rear Door				
13	Right Back Panel	185.6	182	166	209

## Overall Evaluation :

**B**

### Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

<b>Interior Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">A</span>	<b>Exterior Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">D</span>
 <p><b>a</b> : Cut, Fray <b>d</b> : Loose, Deformed <b>k</b> : Animal Hair <b>s</b> : Smell <b>t</b> : Cigarette Burns <b>x</b> : Defective <b>y</b> : Stain</p>	 <p><b>A</b> : Scratch <b>AU</b> : Scratch &amp; Dent <b>B</b> : Modified <b>C</b> : Corrosion <b>G</b> : Stone chip <b>P</b> : Faded <b>S</b> : Rust <b>SC</b> : Rust &amp; Corrosion <b>U</b> : Dent <b>X</b> : Defective <b>Y</b> : Crack, Gap</p>
<b>Remarks</b> Rear Seat - Grime - Small / Ceiling - Grime - Small	<b>Remarks</b> Front Panel - Repair Traces - Yes / (L) Rear Corner Panel - Repair Traces - Yes / (R) Front Fender, Molding - Scratch - Small / (R) Center Panel - Scratch - Minimal / (R) Side Gate - Scratch & Dent - Medium / Cargo Bed Floor - Scratch & Dent - Large / Rear Bumper, Lamps, Panels - Rust, Corrosion - Large / Rear Gate - Scratch - Small / (L) Side Gate - Scratch - Small / Front Panel - Scratch - Small / Front Bumper, Grille, Lamps - Scratch - Small / (L) Front Fender, Molding - Scratch - Minimal / (L) Front Door, Molding - Scratch - Small / Roof - Scratch & Dent - Large
<b>Frame Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">A</span>	<b>Functional Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">A</span>
<b>Remarks</b> Defects not found	<b>Remarks</b> Reverse Camera - N/A - Yes

<b>Inspector Notes</b>
with warranty booklet, no jack, with tools, with spare tire, with LTO plate