

## General Information

Date & Time: 03, Jun, 2025 09:33

<b>Make</b>	Toyota	<b>Model</b>	Vios
<b>YOM</b>	2024	<b>Odo Meter Reading</b>	23,133
<b>Registration No.</b>	NHM6317	<b>Chassis No.</b>	PA1B18F33R4239946
<b>CC</b>	1.3	<b>Transmission</b>	CVT
<b>Fuel Type</b>	Gas	<b>Type of Body</b>	Sedan
<b>Colour</b>	Red		

## Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	<b>112.3</b>	118	104	115
2	Boot Lid	<b>108.3</b>	104	109	112
3	Roof	<b>108.1</b>	105	123	98/107
4	Left Front Fender	<b>100.8</b>	100	99	104
5	Left Front Door	<b>118.3</b>	134	114	107
6	Center Panel Left				
7	Left Rear Door	<b>110.0</b>	106	116	108
8	Left Back Panel	<b>117.3</b>	112	123	117
9	Right Front Fender	<b>103.6</b>	100	104	107
10	Right Front Door	<b>107.0</b>	109	107	105
11	Center Panel Right				
12	Right Rear Door	<b>106.0</b>	103	107	108
13	Right Back Panel	<b>114.0</b>	113	111	118

## Overall Evaluation :

**A**

### Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

<b>Interior Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">A</span>	<b>Exterior Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">C</span>
 <p><b>a</b> : Cut, Fray <b>d</b> : Loose, Deformed <b>k</b> : Animal Hair <b>s</b> : Smell <b>t</b> : Cigarette Burns <b>x</b> : Defective <b>y</b> : Stain</p>	 <p><b>A</b> : Scratch <b>AU</b> : Scratch &amp; Dent <b>B</b> : Modified <b>C</b> : Corrosion <b>G</b> : Stone chip <b>P</b> : Faded <b>S</b> : Rust <b>SC</b> : Rust &amp; Corrosion <b>U</b> : Dent <b>X</b> : Defective <b>Y</b> : Crack, Gap</p>
<p><b>Remarks</b> Ceiling - Grime - Small / (L) Front Floor Mat - Worked - Small / Rear Seat - Grime - Small / (R) Front Seat - Grime - Small</p>	<p><b>Remarks</b> Roof - Dent - Small / (L) Step, In-panel, Side Spoiler - Repair mark - Yes / (L) Rear Door, Molding - Scratch - Minimal / (L) Rear Fender, Molding - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch - Medium / (R) Front Fender, Molding - Crack, Gap - Medium / Bonnet, Headlight - Scratch - Small / (R) Front Door, Molding - Scratch - Small / (R) Rear Door, Molding - Scratch - Small / (R) Rear Fender, Molding - Scratch - Small / Trunk Hood, Rear Gate - Scratch - Small / Rear Bumper, Lamps, Panels - Scratch - Medium</p>
<b>Frame Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">A</span>	<b>Functional Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">A</span>
<p><b>Remarks</b> Defects not found</p>	<p><b>Remarks</b> Spare Key - Issue - Unexist</p>

<p><b>Inspector Notes</b></p>
<p>With warranty booklet and LTO plate, Spare tire. no Tools and Jack. scratch tail lights.</p>