

General Information

Date & Time: 19, Oct, 2024 11:20

Make	Toyota	Model	Vios
YOM	2024	Mileage	4,878
Registration No.	DBM6507	Chassis No.	PA1B18F32R4244233
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Black		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	168.3	177	158	170
2	Boot Lid	167.0	160	168	173
3	Roof	170.0	179	177	154/170
4	Left Front Fender	145.6	148	148	141
5	Left Front Door	159.6	164	163	152
6	Center Panel Left				
7	Left Rear Door	153.6	155	156	150
8	Left Back Panel	161.0	177	158	148
9	Right Front Fender	165.0	167	162	166
10	Right Front Door	158.0	156	156	162
11	Center Panel Right				
12	Right Rear Door	169.6	167	163	179
13	Right Back Panel	163.0	158	157	174

Overall Evaluation :

B

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : B	Exterior Evaluation : C
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Overall Interior - Animal Hair - Yes	Remarks Front Bumper, Grille, Lamps - Scratch & Dent - Large / (L) Mirror - Scratch - Small / (L) Front Door, Molding - Scratch - Minimal / Rear Bumper, Lamps, Panels - Scratch - Small / (R) Rear Fender, Molding - Scratch & Dent - Minimal / Trunk Hood, Rear Gate - Scratch & Dent - Small
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Defects not found

Inspector Notes

more light scratches at the front bumper and rear trunk. swirl marks and hairline scratches around the exterior. Low washer fluid level.