

General Information

Date & Time: 30, May, 2025 13:03

Make	Toyota	Model	Lite Ace
YOM	2023	Odo Meter Reading	11,827
Registration No.	DBH9930	Chassis No.	MHKU3FE10PK003627
CC	1.5	Transmission	M/T
Fuel Type	Gas	Type of Body	Van
Colour	White		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	61.8	62	61	63
2	Boot Lid	51.2	50	46	58
3	Roof	60.8	62	61	52/68
4	Left Front Fender	56.8	61	55	55
5	Left Front Door	58.1	64	57	53
6	Center Panel Left				
7	Left Rear Door				
8	Left Back Panel	77.5	69	68	95
9	Right Front Fender	62.8	73	64	52
10	Right Front Door	51.3	51	50	53
11	Center Panel Right				
12	Right Rear Door				
13	Right Back Panel	171.6	123	146	246

Overall Evaluation :

A

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : A	Exterior Evaluation : B
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
Remarks Defects not found	Remarks (R) Rear Corner Panel - Repair Traces - Yes / (L) Front Door, Molding - Scratch - Small / (L) Front Fender, Molding - Scratch - Small / (L) Rear Wheel, Cover - Scratch, Corrosion - Small / (R) Front Fender, Molding - Scratch - Small / (R) Front Door, Molding - Scratch & Dent - Small / (R) Rear Wheel, Cover - Scratch, Corrosion - Small / Rear Gate - Scratch - Small / Front Panel - Scratch - Small / Roof - Scratch - Small
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Reverse Camera - N/A - Yes

Inspector Notes
With warranty booklet and LTO plate, Jack and sparetire,tools. scratch tail light. adhesive mark on front left flooring.