

## General Information

Date & Time: 23, May, 2025 09:30

<b>Make</b>	Toyota	<b>Model</b>	Avanza
<b>YOM</b>	2019	<b>Mileage</b>	93,428
<b>Registration No.</b>	NBQ3853	<b>Chassis No.</b>	MHKM5EE2FKK013138
<b>CC</b>	1.3	<b>Transmission</b>	M/T
<b>Fuel Type</b>	Gas	<b>Type of Body</b>	MPV
<b>Colour</b>	Silver		

## Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	110.0	106	117	107
2	Boot Lid	117.0	104	133	114
3	Roof	94.2	77	99	102/99
4	Left Front Fender	119.6	112	124	123
5	Left Front Door	95.8	105	95	88
6	Center Panel Left				
7	Left Rear Door	95.7	95	95	97
8	Left Back Panel	112.2	90	126	121
9	Right Front Fender	97.7	102	99	92
10	Right Front Door	86.6	84	88	88
11	Center Panel Right				
12	Right Rear Door	145.0	139	155	141
13	Right Back Panel	128.3	138	135	112

## Overall Evaluation :

**A**

### Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

<b>Interior Evaluation :</b>	<b>B</b>	<b>Exterior Evaluation :</b>	<b>B</b>
<p><b>a</b> : Cut, Fray <b>d</b> : Loose, Deformed <b>k</b> : Animal Hair <b>s</b> : Smell <b>t</b> : Cigarette Burns <b>x</b> : Defective <b>y</b> : Stain</p>		<p><b>A</b> : Scratch <b>AU</b> : Scratch &amp; Dent <b>B</b> : Modified <b>C</b> : Corrosion <b>G</b> : Stone chip <b>P</b> : Faded <b>S</b> : Rust <b>SC</b> : Rust &amp; Corrosion <b>U</b> : Dent <b>X</b> : Defective <b>Y</b> : Crack, Gap</p>	
<p><b>Remarks</b> (R) Front Floor Mat - Grime - Medium / Rear Seat - Grime - Medium / Ceiling - Grime - Medium / (L) Front Seat - Grime - Small / Sunvisor, Sunglass Holder - Crinkle - Medium</p>		<p><b>Remarks</b> (L) Front Fender, Molding - Dent - Small / (R) Mirror - Scratch - Minimal / (L) Rear Door, Molding - Dent - Minimal / Rear Bumper, Lamps, Panels - Scratch &amp; Dent - Small / Bonnet, Headlight - Dent - Minimal / (L) Mirror - Scratch - Minimal / (L) Front Door, Molding - Scratch - Small / Front Bumper, Grille, Lamps - Scratch - Small / Roof - Dent - Small</p>	
<b>Frame Evaluation :</b>	<b>A</b>	<b>Functional Evaluation :</b>	<b>A</b>
<p><b>Remarks</b> Defects not found</p>		<p><b>Remarks</b> Remote Key &amp; Smart entry - Issue - Yes / Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist</p>	

## Inspector Notes

Without warranty booklet, jack and tools. With spare tire. With LTO PLATE.