

General Information

Date & Time: 04, Jun, 2025 17:15

Make	Suzuki	Model	Carry
YOM	2024	Odo Meter Reading	19,319
Registration No.	NKC5903	Chassis No.	MHYDC61T7RJ212014
CC	1.5	Transmission	M/T
Fuel Type	Gas	Type of Body	Van
Colour	White		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	110.3	118	102	111
2	Boot Lid	183.3	187	184	179
3	Roof	108.0	119	103	108/102
4	Left Front Fender	110.3	102	115	114
5	Left Front Door	103.7	92	112	107
6	Center Panel Left	113.0	124	117	98
7	Left Rear Door				
8	Left Back Panel	247.6	229	246	268
9	Right Front Fender	112.3	102	116	119
10	Right Front Door	94.2	93	104	85
11	Center Panel Right	105.2	107	116	93
12	Right Rear Door				
13	Right Back Panel	198.0	189	185	220

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : C
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks Overall Interior - Smell - Yes / Overall Interior - Worn as per age - Yes</p>	<p>Remarks (L) Rear Corner Panel - Repair Traces - Yes / (R) Rear Corner Panel - Repair Traces - Yes / (R) Mirror - Scratch - Small / (R) Side Gate - Scratch & Dent - Large / Rear Bumper, Lamps, Panels - Rust, Corrosion - Large / Cargo Bed Floor - Rust, Corrosion - Large / Front Bumper, Grille, Lamps - Scratch & Dent - Medium</p>
Frame Evaluation : B	Functional Evaluation : A
<p>Remarks Center Floor Panel - Bulge (Cuts, Major Deforms) or Corrosion ? - Yes</p>	<p>Remarks Reverse Camera - N/A - Yes</p>

<p>Inspector Notes</p>
<p>no warranty booklet, no jack, no tools, with spare tire, with LTO plate, possible flooding</p>