

## General Information

Date & Time: 04, Jun, 2025 10:50

Make	Toyota	Model	Vios
YOM	2024	Odo Meter Reading	28,684
Registration No.	NHM1420	Chassis No.	PA1B18F39P4234151
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Black		

## Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	118.3	123	112	120
2	Boot Lid	108.3	105	102	118
3	Roof	114.2	122	112	108/115
4	Left Front Fender	107.0	104	119	98
5	Left Front Door	108.3	110	107	108
6	Center Panel Left				
7	Left Rear Door	111.6	125	109	101
8	Left Back Panel	127.3	136	119	127
9	Right Front Fender	109.0	109	111	107
10	Right Front Door	108.3	114	102	109
11	Center Panel Right				
12	Right Rear Door	115.3	100	111	135
13	Right Back Panel	112.0	107	113	116

Overall Evaluation :

**B**

### Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

<b>Interior Evaluation :</b>	C	<b>Exterior Evaluation :</b>	B
<p><b>a</b> : Cut, Fray <b>d</b> : Loose, Deformed <b>k</b> : Animal Hair <b>s</b> : Smell <b>t</b> : Cigarette Burns <b>x</b> : Defective <b>y</b> : Stain</p>		<p><b>A</b> : Scratch <b>AU</b> : Scratch &amp; Dent <b>B</b> : Modified <b>C</b> : Corrosion <b>G</b> : Stone chip <b>P</b> : Faded <b>S</b> : Rust <b>SC</b> : Rust &amp; Corrosion <b>U</b> : Dent <b>X</b> : Defective <b>Y</b> : Crack, Gap</p>	
<p><b>Remarks</b> (R) Front Seat - Grime - Medium / (L) Front Seat - Cigarette Burns - Burnt, Hole / Rear Seat - Grime - Small / (R) Front Trim - Grime - Minimal / (L) Rear Trim - Cut, Crack - Minimal / (L) Front Trim - Grime - Small / Console, Switches, Vents - Traces of Adhesive Tape - Yes</p>		<p><b>Remarks</b> (R) Front Door, Molding - Scratch - Small / (R) Rear Door, Molding - Scratch - Small / (R) Rear Fender, Molding - Scratch - Small / Rear Bumper, Lamps, Panels - Scratch - Small / (L) Rear Fender, Molding - Scratch - Minimal / (L) Rear Door, Molding - Scratch - Small / (L) Front Door, Molding - Scratch - Small / (L) Mirror - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch - Minimal / Bonnet, Headlight - Scratch - Small / Front Windshield - Scratch, Stone chip - Small</p>	
<b>Frame Evaluation :</b>	A	<b>Functional Evaluation :</b>	A
<p><b>Remarks</b> Defects not found</p>		<p><b>Remarks</b> Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist</p>	

<b>Inspector Notes</b>
with warranty booklet, with jack, no tools, with spare tire, with LTO plate,