

## General Information

Date & Time: 30, May, 2025 09:54

<b>Make</b>	Mitsubishi	<b>Model</b>	Mirage
<b>YOM</b>	2023	<b>Odo Meter Reading</b>	29,358
<b>Registration No.</b>	NIR4364	<b>Chassis No.</b>	PAEA13TJPPA008610
<b>CC</b>	1.2	<b>Transmission</b>	CVT
<b>Fuel Type</b>	Gas	<b>Type of Body</b>	Sedan
<b>Colour</b>	Gray		

## Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	<b>118.0</b>	123	117	114
2	Boot Lid	<b>113.6</b>	114	123	104
3	Roof	<b>104.7</b>	104	110	102/103
4	Left Front Fender	<b>112.0</b>	114	113	109
5	Left Front Door	<b>110.3</b>	110	110	111
6	Center Panel Left				
7	Left Rear Door	<b>102.3</b>	105	101	101
8	Left Back Panel	<b>112.6</b>	114	110	114
9	Right Front Fender	<b>114.6</b>	107	113	124
10	Right Front Door	<b>146.6</b>	152	140	148
11	Center Panel Right				
12	Right Rear Door	<b>147.0</b>	137	141	163
13	Right Back Panel	<b>133.3</b>	134	125	141

Overall Evaluation :

**B**

### Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

<b>Interior Evaluation :</b> <span style="float: right;"><b>B</b></span>	<b>Exterior Evaluation :</b> <span style="float: right;"><b>C</b></span>
 <p><b>a</b> : Cut, Fray <b>d</b> : Loose, Deformed <b>k</b> : Animal Hair <b>s</b> : Smell <b>t</b> : Cigarette Burns <b>x</b> : Defective <b>y</b> : Stain</p>	 <p><b>A</b> : Scratch <b>AU</b> : Scratch &amp; Dent <b>B</b> : Modified <b>C</b> : Corrosion <b>G</b> : Stone chip <b>P</b> : Faded <b>S</b> : Rust <b>SC</b> : Rust &amp; Corrosion <b>U</b> : Dent <b>X</b> : Defective <b>Y</b> : Crack, Gap</p>
<p><b>Remarks</b> (R) Front Seat - Grime - Medium / Rear Seat - Grime - Medium / Mat Other - Grime - Small / (L) Front Seat - Grime - Medium</p>	<p><b>Remarks</b> (R) Front Fender, Molding - Dent - Medium / (L) Mirror - Scratch - Small / (L) Front Fender, Molding - Dent - Small / (L) Rear Fender, Molding - Dent - Small / (L) Rear Door, Molding - Scratch - Small / (L) Front Door, Molding - Scratch &amp; Dent - Small / Rear Bumper, Lamps, Panels - Scratch - Medium / (R) Rear Door, Molding - Scratch - Small</p>
<b>Frame Evaluation :</b> <span style="float: right;"><b>A</b></span>	<b>Functional Evaluation :</b> <span style="float: right;"><b>C</b></span>
<p><b>Remarks</b> Defects not found</p>	<p><b>Remarks</b> Warning Lamps - Issue - Yes / Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist</p>

<p><b>Inspector Notes</b></p>
<p>Maintinance warning lamp. Without warranty booklet, jack, tools and seat cover. With spare tire. 1 key,. With LTO plate.</p>