

General Information

Date & Time: 30, May, 2025 15:08

Make	Hyundai	Model	Eon
YOM	2018	Odo Meter Reading	58,145
Registration No.	NCT6766	Chassis No.	MALA251AAJM572624
CC	0.8	Transmission	M/T
Fuel Type	Gas	Type of Body	Hatchback
Colour	White		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	93.6	89	101	91
2	Boot Lid	212.0	217	211	208
3	Roof	86.2	84	92	84/86
4	Left Front Fender	151.0	148	160	145
5	Left Front Door	152.3	144	138	175
6	Center Panel Left				
7	Left Rear Door	158.3	182	144	149
8	Left Back Panel	138.6	149	130	137
9	Right Front Fender	107.5	99	121	103
10	Right Front Door	104.6	109	99	106
11	Center Panel Right				
12	Right Rear Door	102.3	99	101	107
13	Right Back Panel	98.7	96	98	102

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : D
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks Ceiling - Grime - Small / (L) Front Seat - Cut, Crack - Medium / (L) Front Floor Mat - Grime - Medium / Rear Seat - Grime - Minimal / (R) Front Seat - Cut, Crack - Medium</p>	<p>Remarks Trunk Hood, Rear Gate - Repair Traces - Yes / Roof - Scratch & Dent - Medium / (L) Mirror - Scratch - Small / Front Bumper, Grille, Lamps - Scratch & Dent - Large / (L) Rear Door, Molding - Scratch - Medium / (R) Mirror - Scratch - Medium / Bonnet, Headlight - Scratch - Medium / (R) Rear Door, Molding - Scratch - Medium / Rear Bumper, Lamps, Panels - Scratch - Medium</p>
Frame Evaluation : A	Functional Evaluation : C
<p>Remarks Defects not found</p>	<p>Remarks Power Window (each) - Stuck, Gap - Yes / Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist</p>

<p>Inspector Notes</p>
<p>Gap at front bumper issue. without warranty booklet, seat cover and tools. With jack and spare tire,. 1 key. with LTO plate</p>