


General Information

Date & Time: 31, May, 2025 08:05

Make	Nissan	Model	Navara
YOM	2018	Odo Meter Reading	118,125
Registration No.	NCU3065	Chassis No.	MNTCC2D23Z0036813
CC	2.5	Transmission	A/T
Fuel Type	Diesel	Type of Body	Pickup
Colour	Black		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	106.3	105	104	110
2	Boot Lid	182.3	102	105	340
3	Roof	85.0	76	90	85/90
4	Left Front Fender	101.5	103	104	98
5	Left Front Door	91.4	93	90	91
6	Center Panel Left				
7	Left Rear Door	95.8	99	99	90
8	Left Back Panel	94.5	94	96	94
9	Right Front Fender	96.7	96	101	94
10	Right Front Door	97.2	91	99	102
11	Center Panel Right				
12	Right Rear Door	98.8	95	100	101
13	Right Back Panel	96.9	104	96	91

Overall Evaluation :

D

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : E
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Ceiling - Grime - Medium / (R) Front Trim - Grime - Small / (R) Front Seat - Grime - Medium / Rear Seat - Grime - Medium / (R) Rear Trim - Grime - Small / (L) Front Seat - Grime - Medium / Dashboard - Traces of Adhesive Tape - Yes	Remarks Rear Gate - Repair mark - Yes / (L) Front Fender, Molding - Repair mark - Yes / (L) Side Gate - Scratch & Dent - Large / (L) Rear Door, Molding - Scratch & Dent - Large / (L) Front Fender, Molding - Scratch - Medium / Bonnet, Headlight - Dent - Small / Front Bumper, Grille, Lamps - Scratch & Dent - Large / (R) Front Fender, Molding - Scratch & Dent - Small / (R) Front Door, Molding - Scratch - Medium / (R) Rear Door, Molding - Repair mark - Yes / (R) Rear Door, Molding - Scratch - Small / (R) Side Gate - Scratch - Large / Rear Bumper, Lamps, Panels - Scratch & Dent - Large / Rear Gate - Scratch - Medium / Cab Back Panel - Scratch & Dent - Large / Roof - Dent - Small
Frame Evaluation : A	Functional Evaluation : C
Remarks Defects not found	Remarks Air Conditioner - Function - Weak / Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist

Inspector Notes

Gap at front bumper. rear bumper partially missing. Without warranty booklet, tools and jack. with spare tire. 1 key. with LTO plate