

## General Information

Date & Time: 31, May, 2025 08:41

<b>Make</b>	Mitsubishi	<b>Model</b>	Montero SPT
<b>YOM</b>	2022	<b>Odo Meter Reading</b>	84,418
<b>Registration No.</b>	EAF1917	<b>Chassis No.</b>	MMBGJKR10NH012411
<b>CC</b>	2.5	<b>Transmission</b>	M/T
<b>Fuel Type</b>	Diesel	<b>Type of Body</b>	SUV
<b>Colour</b>	Silver		

## Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	119.3	113	131	114
2	Boot Lid	101.8	101	105	100
3	Roof	95.8	89	93	102/100
4	Left Front Fender	103.4	108	105	97
5	Left Front Door	105.0	105	110	100
6	Center Panel Left				
7	Left Rear Door	91.8	99	87	89
8	Left Back Panel	91.0	94	91	89
9	Right Front Fender	101.2	95	104	105
10	Right Front Door	98.2	101	93	101
11	Center Panel Right				
12	Right Rear Door	97.9	92	98	104
13	Right Back Panel	92.7	96	90	92

**Overall Evaluation :**

B

### Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

<b>Interior Evaluation :</b> <span style="float: right;"><b>B</b></span>	<b>Exterior Evaluation :</b> <span style="float: right;"><b>C</b></span>
 <p><b>a</b> : Cut, Fray <b>d</b> : Loose, Deformed <b>k</b> : Animal Hair <b>s</b> : Smell <b>t</b> : Cigarette Burns <b>x</b> : Defective <b>y</b> : Stain</p>	 <p><b>A</b> : Scratch <b>AU</b> : Scratch &amp; Dent <b>B</b> : Modified <b>C</b> : Corrosion <b>G</b> : Stone chip <b>P</b> : Faded <b>S</b> : Rust <b>SC</b> : Rust &amp; Corrosion <b>U</b> : Dent <b>X</b> : Defective <b>Y</b> : Crack, Gap</p>
<p><b>Remarks</b> Ceiling - Grime - Medium / (R) Front Trim - Grime - Small / Dashboard - Traces of Adhesive Tape - Yes / (R) Front Seat - Grime - Medium / Rear Seat - Grime - Medium / (L) Front Trim - Grime - Small / (L) Front Floor Mat - Missing - Yes</p>	<p><b>Remarks</b> Front Bumper, Grille, Lamps - Repair mark - Yes / Front Bumper, Grille, Lamps - Scratch &amp; Dent - Large / (L) Rear Fender, Molding - Scratch &amp; Dent - Small / (R) Front Door, Molding - Repair mark - Yes / (R) Front Door, Molding - Scratch - Small / (R) Step, In-panel, Side Spoiler - Repair mark - Yes / (R) Rear Door, Molding - Scratch - Minimal / (R) Rear Fender, Molding - Scratch - Small / Rear Bumper, Lamps, Panels - Repair mark - Yes / Rear Bumper, Lamps, Panels - Scratch - Small / (L) Step, In-panel, Side Spoiler - Scratch - Small / (L) Front Door, Molding - Dent - Small / Roof - Dent - Small</p>
<b>Frame Evaluation :</b> <span style="float: right;"><b>A</b></span>	<b>Functional Evaluation :</b> <span style="float: right;"><b>B</b></span>
<p><b>Remarks</b> Defects not found</p>	<p><b>Remarks</b> Battery - Weak - Yes / Spare Key - Issue - Unexist</p>

<p><b>Inspector Notes</b></p>
<p>Without warranty booklet, seat cover and jack. with spare tire and tools. 1 key. with LTO plate.</p>