

General Information

Date & Time: 03, Jun, 2025 17:00

Make	Honda	Model	City
YOM	2021	Odo Meter Reading	59,813
Registration No.	NGL5279	Chassis No.	MRHGN2690MT060437
CC	1.5	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Red		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	110.3	118	104	109
2	Boot Lid	110.6	108	111	113
3	Roof	102.1	99	100	104/106
4	Left Front Fender	105.6	102	106	109
5	Left Front Door	176.5	337	97	96
6	Center Panel Left				
7	Left Rear Door	175.0	191	170	164
8	Left Back Panel	165.0	166	159	170
9	Right Front Fender	99.7	101	99	99
10	Right Front Door	97.0	101	92	98
11	Center Panel Right				
12	Right Rear Door	315.6	148	162	637
13	Right Back Panel	186.3	162	163	234

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation :	C	Exterior Evaluation :	C
<p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>		<p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>	
<p>Remarks (R) Front Seat - Grime - Small / (L) Front Floor Mat - Worked - Small / Overall Interior - Worn as per age - Yes / Overall Interior - Animal Hair - Yes</p>		<p>Remarks (L) Front Door - Repair Traces - Yes / (L) Rear Door - Repair Traces - Yes / (R) Rear Fender - Repair Traces - Yes / (R) Rear Door - Repair Traces - Yes / (L) Front Door, Molding - Repair mark - Yes / (L) Rear Door, Molding - Repair mark - Yes / (R) Rear Door, Molding - Repair mark - Yes / (R) Rear Fender, Molding - Repair mark - Yes / (R) Step, In-panel, Side Spoiler - Dent - Small / (R) Front Door, Molding - Dent - Minimal / Rear Bumper, Lamps, Panels - Repair mark - Yes / (L) Front Fender, Molding - Scratch - Minimal / Bonnet, Headlight - Scratch - Small / (L) Front Door, Molding - Scratch - Small / (L) Rear Door, Molding - Scratch - Small / Trunk Hood, Rear Gate - Scratch - Minimal / (L) Rear Fender, Molding - Scratch - Medium / (R) Mirror - Scratch - Minimal / (L) Mirror - Scratch - Minimal / (R) Front Fender, Molding - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch - Medium</p>	
Frame Evaluation :	A	Functional Evaluation :	A
<p>Remarks Defects not found</p>		<p>Remarks Spare Key - Issue - Unexist</p>	

Inspector Notes
with warranty booklet and LTO plate, Jack and sparetire, Incomplete tools. scratch tail light.