

General Information

Date & Time: 05, Jun, 2025 08:15

Make	Toyota	Model	Avanza
YOM	2010	Odo Meter Reading	144,000
Registration No.	NQL623	Chassis No.	MHFM1BE2F8K013543
CC	1.3	Transmission	M/T
Fuel Type	Gas	Type of Body	Wagon
Colour	Silver		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	158.6	156	159	161
2	Boot Lid	91.0	87	96	90
3	Roof	113.0	89	99	137/128
4	Left Front Fender	518.6	210	179	1,167
5	Left Front Door	133.0	114	124	161
6	Center Panel Left				
7	Left Rear Door	174.0	148	226	148
8	Left Back Panel	108.3	106	115	104
9	Right Front Fender	192.3	106	349	122
10	Right Front Door	93.5	97	98	85
11	Center Panel Right				
12	Right Rear Door	100.2	99	107	95
13	Right Back Panel	131.6	149	118	128

Overall Evaluation :

D

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : E
<p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	<p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks Overall Interior - Worn as per age - Yes / Overall Interior - Smell - Yes / Dashboard - Worn, Scratch, Cut, Crack - Small / Ceiling - Grime - Small / (L) Front Seat - Grime - Medium / (R) Front Seat - Worn - Yes / Rear Seat - Grime - Medium / (L) Front Floor Mat - Worked - Large / (L) Front Trim - Worked - Large / (R) Front Trim - Worked - Small</p>	<p>Remarks (R) Front Door - Repair Traces - Yes / (R) Front Fender - Repair Traces - Yes / (L) Front Fender - Repair Traces - Yes / (L) Rear Door - Repair Traces - Yes / Trunk Hood, Rear Gate - Repair Traces - Yes / (R) Rear Door - Repair Traces - Yes / Roof - Repair Traces - Yes / (L) Rear Door, Molding - Repair mark - Yes / (R) Front Door, Molding - Scratch - Medium / (R) Rear Door, Molding - Scratch - Medium / (R) Step, In-panel, Side Spoiler - Repair mark - Yes / (R) Rear Fender, Molding - Scratch - Minimal / Rear Bumper, Lamps, Panels - Scratch - Minimal / (L) Rear Fender, Molding - Scratch & Dent - Medium / (L) Rear Door, Molding - Scratch & Dent - Large / Front Bumper, Grille, Lamps - Repair mark - Yes / (L) Front Fender, Molding - Scratch & Dent - Small / (L) Step, In-panel, Side Spoiler - Repair mark - Yes / (L) Front Door, Molding - Scratch - Small / (L) Front Wheel, Cover - Scratch, Corrosion - Small / (L) Rear Wheel, Cover - Scratch, Corrosion - Small / (R) Rear Wheel, Cover - Scratch, Corrosion - Small / (R) Front Wheel, Cover - Scratch, Corrosion - Small / Front Bumper, Grille, Lamps - Scratch - Medium / Bonnet, Headlight - Scratch - Small / Roof - Scratch - Small / Trunk Hood, Rear Gate - Scratch - Small / (R) Front Fender, Molding - Crack, Gap - Medium</p>
Frame Evaluation : A	Functional Evaluation : C
<p>Remarks Defects not found</p>	<p>Remarks Air Conditioner - Function - Weak / Reverse Camera - N/A - Yes / Lamps (Brake, Tail, Fog) - Issue - Yes / Spare Key - Issue - Unexist</p>

<p>Inspector Notes</p>
<p>no warranty booklet/ no tools/ no jack/ hard to open hood/ crack and scratch on tail light and head light/ reverse light issue/ plate light issue</p>