

## General Information

Date & Time: 07, Jun, 2025 10:04

<b>Make</b>	Toyota	<b>Model</b>	Hilux
<b>YOM</b>	2024	<b>Odo Meter Reading</b>	52,479
<b>Registration No.</b>	BAF7454	<b>Chassis No.</b>	MR0JB8DD6P3224197
<b>CC</b>	2.4	<b>Transmission</b>	A/T
<b>Fuel Type</b>	Diesel	<b>Type of Body</b>	Pickup
<b>Colour</b>	White		

## Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	102.3	101	104	102
2	Boot Lid	97.1	99	91	101
3	Roof	97.6	100	89	104/98
4	Left Front Fender	100.2	108	90	103
5	Left Front Door	93.7	95	94	92
6	Center Panel Left				
7	Left Rear Door	92.1	93	92	92
8	Left Back Panel	97.9	97	97	100
9	Right Front Fender	104.6	106	100	108
10	Right Front Door	94.8	93	94	99
11	Center Panel Right				
12	Right Rear Door	92.1	91	92	94
13	Right Back Panel	105.5	93	112	112

## Overall Evaluation :

**B**

### Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

<b>Interior Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">C</span>	<b>Exterior Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">B</span>
 <p><b>a</b> : Cut, Fray <b>d</b> : Loose, Deformed <b>k</b> : Animal Hair <b>s</b> : Smell <b>t</b> : Cigarette Burns <b>x</b> : Defective <b>y</b> : Stain</p>	 <p><b>A</b> : Scratch <b>AU</b> : Scratch &amp; Dent <b>B</b> : Modified <b>C</b> : Corrosion <b>G</b> : Stone chip <b>P</b> : Faded <b>S</b> : Rust <b>SC</b> : Rust &amp; Corrosion <b>U</b> : Dent <b>X</b> : Defective <b>Y</b> : Crack, Gap</p>
<p><b>Remarks</b>          Ceiling - Grime - Small / (R) Front Trim - Grime - Medium / (R) Rear Trim - Grime - Small / (R) Front Floor Mat - Grime - Small / (L) Rear Trim - Grime - Small / (L) Front Trim - Grime - Medium / (L) Front Seat - Grime - Medium</p>	<p><b>Remarks</b>          (L) Side Gate - Scratch - Small / (R) Side Gate - Scratch - Medium / Bonnet, Headlight - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch - Medium / (R) Front Door, Molding - Dent - Small / Cab Back Panel - Scratch - Small</p>
<b>Frame Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">A</span>	<b>Functional Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">C</span>
<p><b>Remarks</b>          Defects not found</p>	<p><b>Remarks</b>          Power Window (each) - Stuck, Gap - Yes</p>

<p><b>Inspector Notes</b></p>
<p>With warranty booklet, spare tire and seat cover. without tools and jack. 2 keys. with LTO plate</p>