


General Information

Date & Time: 28, Oct, 2024 15:06

Make	Toyota	Model	Vios
YOM	2024	Mileage	6,064
Registration No.	DBM9242	Chassis No.	PA1B18F30R4243890
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Red		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	131.6	130	133	132
2	Boot Lid	130.3	122	132	137
3	Roof	134.7	136	132	130/141
4	Left Front Fender	122.6	126	120	122
5	Left Front Door	123.3	125	120	125
6	Center Panel Left				
7	Left Rear Door	130.0	134	131	125
8	Left Back Panel	132.0	133	131	132
9	Right Front Fender	125.6	132	124	121
10	Right Front Door	128.6	129	130	127
11	Center Panel Right				
12	Right Rear Door	130.6	123	126	143
13	Right Back Panel	133.0	133	128	138

Overall Evaluation :

A

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : A	Exterior Evaluation : C
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Defects not found	Remarks (R) Rear Fender, Molding - Scratch & Dent - Large / Rear Bumper, Lamps, Panels - Scratch - Minimal / (L) Rear Door, Molding - Scratch - Small / (L) Front Door, Molding - Dent - Small / Bonnet, Headlight - Scratch - Minimal / (R) Rear Door, Molding - Scratch - Minimal / Trunk Hood, Rear Gate - Scratch - Minimal / (L) Front Fender, Molding - Scratch - Minimal
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Spare Key - Issue - Unexist

Inspector Notes
slight discolouration between body and bumpers (front and rear)