

## General Information

Date & Time: 07, Jun, 2025 16:01

<b>Make</b>	Mitsubishi	<b>Model</b>	Mirage
<b>YOM</b>	2022	<b>Odo Meter Reading</b>	33,608
<b>Registration No.</b>	NFJ9566	<b>Chassis No.</b>	PAEA13RJNMA023172
<b>CC</b>	1.2	<b>Transmission</b>	M/T
<b>Fuel Type</b>	Gas	<b>Type of Body</b>	Sedan
<b>Colour</b>	Silver		

## Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	<b>105.0</b>	109	106	100
2	Boot Lid	<b>97.6</b>	90	102	101
3	Roof	<b>99.0</b>	98	104	92/102
4	Left Front Fender	<b>109.6</b>	114	107	108
5	Left Front Door	<b>99.9</b>	99	98	103
6	Center Panel Left				
7	Left Rear Door	<b>97.3</b>	101	94	98
8	Left Back Panel	<b>100.3</b>	110	97	94
9	Right Front Fender	<b>98.6</b>	98	99	99
10	Right Front Door	<b>105.0</b>	103	105	107
11	Center Panel Right				
12	Right Rear Door	<b>104.0</b>	101	103	108
13	Right Back Panel	<b>97.4</b>	86	97	109

## Overall Evaluation :

C

### Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

<b>Interior Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">C</span>	<b>Exterior Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">C</span>
 <p><b>a</b> : Cut, Fray <b>d</b> : Loose, Deformed <b>k</b> : Animal Hair <b>s</b> : Smell <b>t</b> : Cigarette Burns <b>x</b> : Defective <b>y</b> : Stain</p>	 <p><b>A</b> : Scratch <b>AU</b> : Scratch &amp; Dent <b>B</b> : Modified <b>C</b> : Corrosion <b>G</b> : Stone chip <b>P</b> : Faded <b>S</b> : Rust <b>SC</b> : Rust &amp; Corrosion <b>U</b> : Dent <b>X</b> : Defective <b>Y</b> : Crack, Gap</p>
<p><b>Remarks</b> Ceiling - Grime - Medium / (R) Front Seat - Grime - Medium / Rear Seat - Grime - Large / Mat Other - Grime - Small / (L) Front Seat - Grime - Medium / (L) Front Floor Mat - Worked - Small / Sunvisor, Sunglass Holder - Crinkle - Small</p>	<p><b>Remarks</b> (R) Front Fender, Molding - Scratch &amp; Dent - Medium / (L) Mirror - Scratch - Small / Rear Bumper, Lamps, Panels - Scratch &amp; Dent - Medium / (R) Front Door, Molding - Scratch &amp; Dent - Small / (R) Rear Door, Molding - Scratch &amp; Dent - Minimal / (R) Rear Fender, Molding - Scratch &amp; Dent - Small / (L) Rear Fender, Molding - Scratch - Small / Trunk Hood, Rear Gate - Dent - Minimal / Front Bumper, Grille, Lamps - Scratch - Small / Roof - Dent - Small</p>
<b>Frame Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">A</span>	<b>Functional Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">C</span>
<p><b>Remarks</b> Defects not found</p>	<p><b>Remarks</b> Air Conditioner - Function - Weak / Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist</p>

<p><b>Inspector Notes</b></p>
<p>aircon weak. with warranty booklet, spare tire,jack and tools. 1 key. with LTO plate.</p>